## CBCS SCHEME

USN										The state of the s	BEE401
-----	--	--	--	--	--	--	--	--	--	--	--------

## Fourth Semester B.E./B.Tech Degree Examination, June/July 2024 Electric Motors

Time: 3 hrs.

Max. Marks: 100

Note: 1. Answer any FIVE full questions, choosing ONE full question from each module.
2. M: Marks, L: Bloom's level, C: Course outcomes.

		A VY			
		Module – 1	M	L	C
Q.1	a.	What is back emf? Explain the significance of back emf in DC motor.	7	L1	CO1
	b.	Explain the different characteristics of DC shunt motor.	6	L2	COI
	c.	A 230V DC shunt motor runs at 800rpm and takes current of 50A. Find the resistance to be added to the field circuit on increase the speed from 800rpm to 1000rpm at an armature current of 80A. Assume flux is proportional to field current. Armature resistance is $0.15\Omega$ and field resistance is $250\Omega$ .	7	L3	C01
	_	OR			
Q.2	a.	Explain the various losses that occur in DC machine. Derive the condition for maximum efficiency of DC motor.	10	L1	CO1
	b.	With a neat diagram, explain the Swimburn's test on a DC motor mention the demerits of this test.	10	L1	CO1
		Module – 2			
Q.3	a.	Explain with help of suitable diagram how rotating magnetic field is produced in a 3 phase induction motor.	6	L1	CO2
	b.	Explain the construction and working of 3-phase induction motor.	8	L2	CO2
	c.	Derive the equation for torque developed by the 3-phase induction motor.	6	L3	CO2
		OR			
Q.4	a.	Discuss the torque-slip characteristics of a 3\$\phi\$ I.m including motoring generating and braking regions.	10	L2	CO2
	b.	A 400V, 3φ, 50Hz star connected I.m has a rotor resistance and reactance per phase equal to 0.01Ω and 0.1Ω respectively. determine:  i) Starting torque  ii) Slip at which maxm torque will occurs  iii) Speed at which maxm torque will occur  iv) Maximum torque  v) Full load torque.  If full load slip is 4%, assume ratio of stator to rotor tunes as 4.	10	L3	CO2
		Module – 3			
Q.5	a.	Starting from the fundamentals, draw and explain the equivalent circuit diagram of 30 \$\phi\$ I m.	10	L2	CO3
	b.	Discuss the losses in 3-phase I.m.	10	L2	CO3
		OR	- 4		- 00
Q.6	a.	Explain the phenomenon of cogging and crawling in a 3-phase induction motor.	8	L2	CO3
	b.	Explain the construction and working of double cage I.m.	6	L2	CO3
	c.	Write short notes on induction generator.	6	L2	CO3
		, ,		75 till 1	

BEE40	BI	CE	4	0	
-------	----	----	---	---	--

				BE	E401
		Module – 4			
0.7		Justify the necessity of starter for 3\phi I.m. Explain star delta starter with	8	L2	CO4
Q.7	a.	neat sketch.		7.75 T.M. 1	
	b.	With a neat diagram, explain the speed control of a 3-\$\phi\$ induction motor	6	L2	CO4
	υ.	using V/f control.			
	c.	A squired cage I.m has a full load slip of 4% and blocked rotor current of	6	L3	CO <sub>4</sub>
		6 times the full load current. Find the percentage of tapping of the auto-			
		transference starter to give full load torque on starting and the line current			
		as a percentage of full load current			
		OR	,	Y 2	COL
Q.8	a.	Explain double revolving theory as applied to a 1-\$\phi\$ induction motor and	6	L2	CO4
		prove that it cannot produce any starting torque.	0	T 4	004
	b.	A 250 watt. 230V, 50Hz single phase capacitor start I.m has the following	8	L4	CO4
		constants for the main and auxiliary windings main winding			
		$Z_m = (4.5 + j3.7)\Omega$ , auxiliary winding $Z_a = (9.5 + j3.5)\Omega$ . Determine the			
		value of the capacitor that will place the main and auxiliary winding			
	_	currents in quadrature at starting.	6	L2	CO4
	c.	With a neat sketch, explain the construction working and applications of	v		
		shaded pole I.m.			
	_	Module – 5			
Q.9	a.	Explain the principle of operation of synchronous motor at constant load	8	L2	COS
Q.		variable excitation.			
	b.	True A Cormohagaga mater	6	L3	CO5
	c.	What is a synchronous condenser and its uses.	6	L2	CO5
Device and		OR OR			
Q.10	a.	With a neat sketch, explain the construction and working of universal	8	L2	CO5
		motor.		-	-
	b.	With a neat sketch, explain the construction and working of linear induction	6	L2	CO5
		motor.	-	7.3	COS
	c.	With a neat diagram, explain the construction and working of switched	6	L2	COS
		reluctance motor.			
		****	-		
		1, 00			
		X			
		The second secon			
		A CONTRACTOR OF THE PARTY OF TH			
		0.00			
		2 of 2			
		1			
		3			