Figure 1: Door Open Detection with Blue LED Indication
The door status is detected using the HC-SR04 Ultrasonic Sensor. When the door is open, the LCD displays **"Door is OPEN"**, and the **Blue LED lights up** to indicate the open-door condition.



Figure 2: When the door is detected as open by the HC-SR04 Ultrasonic Sensor connected to the ESP32, the **Blue LED turns ON** and the LCD shows **"Door is OPEN"**. After **3 seconds**, the **Blue LED turns OFF** and the LCD displays **"Close the Door"**.



Figure 3: High Temperature and Humidity Alert with Red LED
When the temperature and humidity exceeds the threshold values measured by the DHT22 connected to the ESP32, the **Red LED turns ON** and the LCD displays the current temperature and humidity values.



Figure 4: Normal Storage Condition with Green LED Indicator
When the temperature and humidity values measured by the DHT22 connected to the ESP32 are **within the threshold limits**, the LCD displays **"Storage Normal"** and the **Green LED turns ON** to indicate safe storage conditions.