
Torqeedo High Tension Layout

Iguana Original #20


Summary

- List of component with HT wiring:
  - 1 battery
  - 2 track's variator & track motors
  - 2 HT junction box **TO BE SENT**
  - 1 hydraulic pump variator & hydraulic pump
  - 1 HV fusebox (to be add)
  - 1 HV charger (to be changed)
  - 1 400 V / 12V converter

HT Layout


Hydraulic Pump
HVLP Sevcon (PUMP)
Track Motor PORT
Junction Box PORT
Variator Zapi PORT
DC/DC 400 / 12 V
Track Motor STBD
Junction Box STBD
Variator Zapi STBD
Fusebox
Torqeedo Battery
Charger 400V

HT Fusebox


DC/DC
HVLP Sevcon
Battery +
Battery -
FUSE 20A
FUSE 30A
FUSE 200A
FUSE 200A
Mass
Charger 400V
Zapi Port +
Zapi Stbd +
Zapi Port -
Zapi Stbd -