MeshSync rejoin incident

[SAMPLE] Fictional Aurora Labs company record. Not research findings.

Record	INC-2026-017
Date	2026-09-18
Owner	Mira Chen
Project	Aurora Labs / GH-03

Context

At GH-03, an eight-node run left NW2-008 disconnected after a parent swap. The synthetic field note records a transient current range of 110 to 340 microamps. The six-node baseline does not establish eight-node stability.

Details

Firmware 0.9.4-rc2 is a candidate for retest. The issue remains open. A receipt of the candidate build must not be interpreted as a successful retest or release approval.

Next action

Priya Nair will repeat the eight-node case, capture rejoin timing, and attach the trace. Mira Chen will review the trace before closing INC-2026-017.