Eight node retest status

[SAMPLE] Fictional Aurora Labs company record. Not research findings.

Record	QA-RETEST-021
Date	2026-09-21
Owner	Priya Nair
Project	Aurora Labs / GH-03

Context

The eight-node rejoin retest for INC-2026-017 is blocked because the gateway trace is incomplete. No passing result has been recorded for firmware 0.9.4-rc2.

Details

The six-node run is a separate baseline. Do not generalize it to eight or ten nodes. The release checklist remains on hold until the missing trace and repeat run are reviewed.

Next action

Mira Chen must provide the diagnostic build. Marcus Webb must reserve GH-03 access. Priya will add a dated result after the repeat run.