

## **Driver Release Note**

Product: FL1000 Series

Driver Version (Windows): 3.0.89.14

Release Date: 2010/04/19

## **Revision History**

Version	Issue Date	Comment
2.1.0.17	2009/9/15	Initial release by Fresco Logic
2.2.0.20	2009/9/25	Enhance USB 2.0 compatibility
		Enhance plug/unplug stabilities
		Add support to FullSpeed devices
		Compact binary code
2.6.0.41	2009/10/20	Enhance USB2.0 compatibility
		Fix the Resume issue for some devices
2.8.0.56	2009/11/24	Fix the driver installation issue for WinXP
		Fix the unplug/plug unstable issue
2.14.0.68	2009/12/30	Iso transfer support for MP version IC
2.14.0.76	2010/02/05	WHQL pass (WLK1.4)
		Support hub
		Fix resume, disable, plug issue
2.14.0.79	2010/02/22	Add the XP icon
		Support for Bandwidth limitations.
3.0.86.14	2010/04/01	Enhance the stability of plug/unplug, reboot, resume of USB3.0/2.0
		devices
3.0.89.14	2010/04/19	WLK1.5 support (WHQL certified)
		Fix bugs:
		printer unplug hang
		verifier crash and blue screen
		Enhance the warm reboot stability of Cyberslim device
		Add support for devices that use scatter/gather lists for control endpoints.



## **Driver Package**

There are four drivers in one package (driver version is 3.0.89.14):

308914\_32bit\_Vista.msi: Driver for Windows Vista 32bit OS

308914\_32bit\_W7XP.msi: Driver for both Windows 7 32bit and Windows XP 32bit OS

308914\_64bit\_Vista.msi: Driver for Windows Vista 64bit OS

308914\_64bit\_W7XP.msi: Driver for both Windows 7 64bit and Windows XP 64bit OS

## **Driver Upgrade**

If you install previous version by using inf, please use device manager to uninstall previous version.

If you install previous version by using the install shell, please use control table to uninstall the previous version.

After you uninstall the previous version, you could upgrade the driver by using this latest version 3.0.89.14.