

Project Name: Lohia One
UP RERA Registration No. UPRERAPRJ977450/06/2025
Website of UP RERA: www.up-rera.in
Launch Date: 03-06-2025



Collection A/C Details Of Lohia One:
Bank Account Name: Lohia Developers (India) Pvt. Ltd. collection account for
Account Number: 43711463236
Bank Name: State Bank Of India
IFSC Code: SBIN0004113



*All images shown in this leaflet are for illustration purpose only

JULY 2026

**EXCLUSIVE VILLA
COMMUNITY.**

**CONSTRUCTION UPDATES
OF YOUR FUTURE VILLA.**

NEW MORADABAD

To know more visit www.lohiaworldspace.com or call +91 70 80 90 60 60

LOHIA WORLDSPACE

Lohia Worldspace is committed to creating expansive spaces, with more than adequate space for interaction with gifts of nature, which nurture a sense of belonging and pride. We are dedicated to offering an experience that brings to the table modern amenities and harmony with nature. We endeavour to create a clear distinction from concrete spaces and pave the way for luxury and leisure.

We believe thoughtful architecture that allows enough space for greenery to flourish can go a long way in avoiding monotony, uplifting the mood, and creating a sense of belonging.



Exclusive Villa Community.

Where, Every Home Has

Modern Interiors

Spacious Rooms

Independent Stairs

Open Space

Club House with Amenities

घर हो,
VILLA
JAISA.



CONSTRUCTION UPDATES



Temple (Mandir)

All civil and structural works, along with internal and external plastering works, were completed in the previous months. In July, landscaping works at the front of the Temple were commenced and are currently in progress.



Main Entry

Civil works for the Main Gate foundations commenced in July and are currently in progress. Additionally, landscaping works in front of the Guard Room also commenced in July and are currently ongoing.

CONSTRUCTION UPDATES



Villa A01 to A12

Up to June, plinth beam casting for all villas had been completed. Mivan shuttering and reinforcement works for the ground floor roof slabs of Villas A07 and A08 were in progress. During July, ground floor roof slab casting for Villas A07, A08, A09, and A10 was completed. Mivan shuttering and reinforcement works for the ground floor roof slabs of Villas A11 and A12 are currently in progress.



Villa A13 to A24

Up to June, the ground floor roof slab casting for all 12 villas had been completed, and the first floor roof slab casting for Villas A21 to A24 had also been completed. During July, first floor roof slab casting for Villas A19 and A20 was completed.

CONSTRUCTION UPDATES



Villa A25 to A34

All structural works from the ground floor up to the mumty level for all 10 villas have been completed. Additionally, the front brick-tile façade works for Villas A31 to A34 have also been completed.



Sample Villa A35 and A36

All works, including finishing and interior works, for Sample Villa A36 have been completed. For Lead Villa A35, all finishing works have been completed, while interior works are currently in progress.

CONSTRUCTION UPDATES



Villa A 37 to A44

Ground floor roof slab works for all 6 villas have been completed. First floor roof slab works for 5 out of 6 villas have been completed, while mumty roof slab works for 4 out of 6 villas have been completed to date.



Club One

Raft concrete works were completed in the previous month. During July, reinforcement, shuttering, and concreting works for the basement shear walls, STP tanks, and other water tanks are in progress.

CONSTRUCTION UPDATES



Villa B01 to B32

Plinth beam casting works for all 32 villas have been completed. Additionally, ground floor roof slab works for Villas B13 to B16 have also been completed.



Villa B33 to B58

Plinth beam casting works for Villas B41 to B58 have been completed, while works for the remaining villas are currently in progress. Additionally, ground floor roof slab works for Villas B46 and B47 have also been completed.

CONSTRUCTION UPDATES



Villa C01 to C26

Foundation casting and pedestal works are currently in progress.



Villa C27 to C58

All foundation works, along with soil filling, have been completed. Plinth beam casting works for 14 villas have been completed to date. Ground floor roof slab works for Villas C39 to C43 have also been completed, while Mivan shuttering and reinforcement works for the ground floor roof slabs of Villas C37 and C38 are currently in progress.

CONSTRUCTION UPDATES



Road Construction Work

RCC road works from Villas A31 to A36 have been completed, along with all underground MEP services. Saucer drain and kerb stone fixing works are currently in progress.



Alcohol Test Pic

The significance of alcohol testing at a construction site is to ensure workers are fit for duty, prevent accidents caused by impaired judgment, comply with HSE and contractual requirements, and protect the safety of workers, equipment, and the public

CONSTRUCTION UPDATES



Quality Works Related Training

Site quality training enables the workforce to deliver right-first-time construction, ensuring durable, compliant, and cost-effective project execution.



Reinforcement Quality Used in Slab

Slab reinforcement and electrical conduits have been installed in accordance with approved structural and electrical drawings, maintaining proper spacing, cover, routing, fixing, and coordination to ensure the required structural quality, safety, and durability before concrete pouring.

CONSTRUCTION UPDATES



Safety Training

Regular site safety training promotes hazard awareness and safe behavior, helping achieve zero-accident and uninterrupted project execution.



TMT Tensile Test

Tensile testing of TMT reinforcement bars was conducted using a calibrated Universal Testing Machine to verify strength, ductility, and elongation as per applicable standards.

This quality check ensures the reinforcement steel meets the required specifications and contributes to the safety, strength, and durability of the structure.

CONSTRUCTION UPDATES



Slump Test

The Concrete Slump Test is a simple field test used to measure the workability and consistency of fresh concrete by filling a standard slump cone in layers, compacting each layer, and then lifting the cone to observe the amount the concrete subsides (slump); the result indicates how easily the concrete can be mixed, placed, and compacted, and is commonly performed as per IS 1199 and IS 7320.



Inspection Of Bar bending machine

A proper safety inspection of a rebar/bar bending machine requires checking its physical integrity, electrical connections, emergency controls, and mechanical components to ensure the equipment is fully fit for use.





Kids Area




Open Yoga




Cricket Pitch



Basketball Court



Swimming Pool With Open Sun Deck




Indoor Gym



Indoor Squash Court



Indoor Badminton Court



Private Theatre

Refer & Rejoice

Your Trust Deserves a Reward!

At Lohia One, we believe our happiest customers are our best ambassadors. Now, when you refer someone to us it's not just a gesture, it's a celebration!

HOW IT WORKS:

Share a Genuine Lead: Tell your friends, family, or colleagues about Lohia One.

They Book a Home: Once your referred lead successfully books with us

You Earn

₹ 50,000*

They Save

₹ 100,000*

SIMPLE STEPS:

1. Share your friend's contact details with our CRM team before their first visit.
2. Our team will personally connect with them and assist in their home-buying journey.
3. Once the booking is confirmed and minimum 30% payment is completed, your reward will be processed.

Important Conditions: (a) The referred lead should be exclusive and not associated with any other channel partner, dealer, or reference. (b) The referee's benefit and referrer's reward will be applicable only after 30% of the booking amount is received.

The management reserves the right to verify and validate all referrals.



EXCLUSIVE VILLA COMMUNITY

घर हो,
**VILLA
JAISA.**

New Moradabad

+91 70 80 90 60 60

hello@lohiaworldspace.com

* T/C are applied.

Project Name: Lohia One, Launch Date: 03-06-2025
UP RERA Registration No. UPRERAPRJ977450/06/2025, Website of UP RERA: www.up-rera.in,
Collection A/C Details Of Lohia One:
Bank A/C Name: Lohia Developers (India) Pvt. Ltd. collection account for Lohia One
Account Number: 43711463236, Bank Name: State Bank Of India, IFSC Code: SBIN0004113



TDS PAYMENT INFORMATION

COMPANY AND TDS FILLING DETAILS

Company Name

Lohia Developers (India) Private Limited

Company PAN

AAACL5169Q

ADDRESS AND CONTACT DETAILS

Registered Address

Lakri Fazalpur, Delhi Road,
Moradabad, Uttar Pradesh

Postal Address

Lakri Fazalpur
Delhi Road, Moradabad, Uttar Pradesh

Email Id

lohiadevelopers@yahoo.com

Contact

+91 9990 966 609

INFORMATION AND TUTORIALS

TDS Filing Tutorial

<https://www.incometaxindia.gov.in/tutorials>

Income Tax Compliance Portal

<https://www.incometax.gov.in/iec/foportal/>

Generate Income Tax Form 141 (Earlier Form 26QB)

<https://www.incometax.gov.in/iec/foportal/help/all-topics/e-filing-services/form-141-challan-cum-statement-deduction-tax-us-3931-UM>

Generate Income Tax Form 132 (Earlier Form 16B)

<chrome-extension://efaidnbmnnnibpcajpcglclefindmkaj/https://www.incometaxindia.gov.in/documents/d/guest/fn-130-131-132-133>

For all official TDS payments, use the details provided for our records and for submitting the tax payment. Please contact the company directly if you have any questions or require further information regarding TDS payments.

FINANCE PARTNERS



YOUR CUSTOMER PORTAL

Everything You Need in One Place

Please find below the details that can be viewed and checked through the Customer Portal at:

 <https://server1.farvisioncloud.com/>



Note: For Username & Password please refer to the welcome letter.

Customer Info Section

Home
Applicant Ledger
Outstanding
Late Payment Fee Ledger
Statement of Account
My Generic Document
Project Progress

Document Print Section

Receipt Print
Invoice Print

Attachment Section

Document Attachment

My Queries Section

Query

For your convenience, all the above information is available in the portal link provided.

CONTACT US

CRM Email: crm@lohiaworldspace.com

Contact Person

Mr. Ambuj Tomar
+91 9990 966 609

Scan QR or click *



Customer Testimonials



Township Walkthrough



Founders message



Brand Film



EXCLUSIVE
VILLA COMMUNITY.

Experience Center (Site Office)

Lohia One, Opposite Sector 6,
New Moradabad,
Uttar Pradesh - 244102

Lohia Developers (India) Pvt. Ltd.

3rd Floor, Centrum Plaza Mall,
Khasra No 369-370, Opp. Metro Pillar 16B,
MG Road, Sultanpur, New Delhi, 110030

+91 70 80 90 60 60

Scan QR or click *



lohiaworldspace.com



Township Location

CLICK ICONS TO VISIT
OUR SOCIAL HANDELS

