Work note - Mixer MIX-08
Technician: Carlos Mendes
Replaced 1 agitator shaft seal. Mixer down about 4 hours.
Job finished and tested.