

공정 7. Etching (1): Bulk Micromachining

↗ 관련 과목	
↗ 관련 시험/과제	
> 강의 일자	
늘 상태	완성
❷ 강의자료	

Reminder: General Step

gas의 화학반응을 이용하는 것이 dry, 용액을 이용하는 것이 wet

anisotropic: 방향에 따라 etching 속도 등이 달라짐

isotropic (등감성) : 모든 방향에 대해 같음

한 방향으로 깊이 깎아야 하는 경우 anisotropic을 사용해야 함


1. Micromachining

1) Bulk → Surface

Bulk micromachining

; Bulk micromachining was developed in the late 70's essentially for the fabrication pressure sensor membranes from a silicon monocrystal.

; It is nowadays commonly used to fabricate a variety of mechanical structures (e.g. membranes, valves, and cantilevers) and fluid handling devices (e.g. channels, cavities)




주로 Si wafer를 깎아 만든다고 생각하면 됨

사진과 같은 피라미드 모양으로 깎아서 microfludic channel에 사용할 밸브 제작, 잉크젯 프린터기의 카트리지 밸브 제작 등에 쓰임

Surface micromachining

; Surface micromachining uses several deposition, lithography, and etching processes to build up mechanical features, layer by layer, on a wafer surface.

; It usually requires the use of a sacrificial layer to form cavities or free-standing and moving structures.



주로 MEMS에 사용.

사진은 에어백의 가속도 센서 등에 사용하는 MEMS 구조 beam projector의 pixel 하나하나 구조를 만드는 데도 사용

Bulk ↔ Surface 비교

	Bulk-micromachining	Surface-micromachining
Birth	1960's	1980's
Structure (Material)	Single crystal silicon wafer	Thin film on wafer
Etching	Wet/Dry etching	Wet/Dry etching
Etch control	Crystal orientation, Diffusion layer	Material selectivity

규칙적인 배열 없는, 즉 single crystal이 아닌 물질은 bulk에 사용하기 힘듦. → 주로 Si Wafer에 사용


공정에서의 핵심은 control임. 각 단위 공정에서 매우 중요!

etch control이라는 것은 식각률을 control 한다는 것. 어디는 많이 etch되고 어디는 조금 etch되고를 조절하는 것. Bulk - crystal orientation에 대한 이해로 control & concentration의 높은 부분, 낮은 부분에 따라 control할 수 있음.

Surface - 각 layer의 재료마다 다른 etch rate에 따라 mask는 etch가 안 되고, target sample은 etch가 되는 등 control 할 수 있음. 따라서 재료와 chemical reaction(dry or wet)의 selectivity가 핵심.

2. Bulk Micromachining

Bulk - Applications




80~90년대 응용 사례들. 최근 응용 사례들은 중간고사 이후 살펴볼 예정

- 1) optical 기기에 wave의 guideline을 잡아주는 bench
- 2) 정확히 45도로 기울어진 거울
- 3) 이렇게 각지게 파인 구조
- 4) isotropic한 etching을 사용하면 구 형태 구조물 제작 가능 \rightarrow 5) microlens로 응용
- 6) patterning된 구조도 제작 가능

SiOB(Silicon Optical Bench)에서 파인 부분 (위의 1번과 동일) → 활용해서 transceiver를 제작함.

ATM(Atomic Force Measurement) prode의 뾰죡한 tip 부분 제작

Reminder: Silicon Crystallography



파란 면을 수직으로 single crystal을 바라봤을 때의 모양이 오른쪽 그림

orientation : 방향에 따라 110, 100, 111

같은 Si도 바라보는 방향에 따라 구조가 달라지므로 공정 뿐 아니라 열/전기적 특성도 달라짐


왜 방향에 따라 공정할 때의 식각률(etch rate)이 달라지는가

→ surface density가 달라져서 ("unit cell 원자 개수 ÷ unit cell 면적"으로 구함)

1) Wet Chemical Etching

보통은 wafer를 etch solution에 담금

dry보다 빠름 & higher degree of selectivity 제공함(물질 별로 식각 차이가 많이 나서 좋음)



isotropic etching

모든 방향에 same etch rate \rightarrow 반구 모양 만들 수 있음.

그러나 그림 b 모양이 나오기도 하는데, 그 이유는 etching되고 나온 부산물이 표면에 고여서 etching을 방해하기 때문

 \rightarrow 방지하려면 etching을 하는 동안에 **agitation**을 해줘야 함 (flow를 유도해서 부산물이 떨어져나오게 유도)

anisotropic etching

surface orientation에 따라서 etch rate 달라짐. 100인 면은 111인 면보다 surface density가 2배 가까이 작기 때문에 식각이 더 잘 됨. 그래서 방향에 따라 식각된 모양이 달라질 수 있음.

그림을 보면 111 orientation이 공통적으로 적혀있는데,

bulk machining에서 111 orientation이 가장 etch가 잘 안 되고 남아있는 방향이기 때문에 중요함.

→ 111 방향과 수평면이 이루는 각도가 etch rate 판별에 중요하게 적용됨 (뒤에 더 자세히)

Wet: Isotropic etching

주로 산성 용액 사용: HF / HNO3 / CH3COOH ← ← HNA system이라고 불림.

HNA system : Hydrofluoric acid / Nitric acid / Acetic acid 이 3가지를 섞은 HNA solution이 rounded isotropic 특성을 만듦.

overall reaction of HNA system with silicon:

Nictic이 Si를 만나면 SiO2가 만들어지고, Hydrofluoric이 이걸 없애줌.

→ 최종 반응물로 나온 H2SiF6은 기체라서 날아가고, 물은 이후 반응에 영향 안 줌.

Si+ 4HNO₃
$$\rightarrow$$
 SiO₂ + 2H₂O + 4NO₂ ---- (1)
SiO₂ + 6HF \rightarrow H₂SiF₆ + 2H₂O ---- (2)

어떤 비율로 섞느냐에 따라 달라지는 것 → Silicon의 etch rate

Nitric이 Si를 SiO2로 만드는 가장 큰 역할을 하므로 Nitric 비율이 높을수록 etch rate가 증가함

(100)/(111) etch ratio는 비율 무관하게 1:1로 동일함. isotropic이기 때문임.

masking film의 etch rate도 중요.

- masking을 잘 하기 위해서는 etching할 물질보다 film의 etch rate가 작을수록 좋음.
- Nitric 비율 높을수록 같이 증가하긴 하지만, Si가 0.7 o 7um/min으로 증가할 때, SiO2 film은 30 o 70nm/min으로 증가. Si에 비해 매우 천천히 etch됨.
- Si3N4의 경우 oxidation을 통해 만들 수 없는 물질이기 때문에 etch가 안 됨.

Masking for isotropic silicon etchant

SiO2가 주로 쓰임. etch rate 300~800 A/min (= 30~80 nm/min)

오래, 깊이 etch를 할 때는 nonetching mask 써야 함 → Au, SiN4

용액이 acid이기 때문에 acid에 약한 photoresist(PR)은 mask 역할을 잘 못함. (i.e. HNO3)

<Masking materials for acidic etchants>

Masking	Piranha (4:1, H2O2: H2SO4)	Buffered HF (5:1NH4F: conc. HF)	HNA
Thermal SiO ₂		0.1 μm/min	300-800 Å /min. Limited etch time, thick layers often are used due to ease of patterning.
CVD (450°C) SiO ₂		0.48 µm/min	0.44 μm/min
Corning 7740 glass		0.063 μ/min	1.9 µ/min
Photoresist	Attacks most organic films	OK for short while	Resists do not stand up to strong oxidizing agents like HNO, and are not used.
Undoped Si polysilicon	Forms 30 Å of SiO ₂	0.23 to 0.45 Å/min	0.7 to 40 $\mu m/min$ at RT {at a dopant concentration $<10^{17}$ cm $^{-3}$ (n o p)].
Black wax			Usable at room temperature.
Au/Cr	OK	OK	OK
LPCVD Si ₃ N ₄		1 Å/min	Etch rate is 10-100 Å/min. Preferred masking material.

Note: The many variables involved necessarily mean that the given numbers are approximate only.


acidic etchant에 대한 대표적인 예 : Piranha, Buffered HF, HNA

각각에 대해 masking이 얼마나 etching되는 지를 표로 쓴 것. 잘 고려해서 masking 선택해야 함

Piranha: 화학반응을 통해 유기 물질(대표적인 예: PR)을 태워버림. 실제로 보면 끓으면서 열이 엄청 남.

Buffered HF: etching할 때 대표적으로 사용. 매우 위험한 불산이므로 보호장구 착용 필수 (뼈 녹임)

Wet: Anisotropic etching




100 & 111 : **54.74°**

→ 피라미드 모양으로 etching 됨

110 & 111 : **90°**

→ 수직으로 etching 됨




그림에서 빨간색 그림 : 100 방향으로 들어가면 보이는 111 방향의 모양

KOH를 사용해서 silicon을 etch하는데, etch rate가 위와 같음. (100)과 (111)이 거의 100배 차이나므로 111은 100에 비해서 거의 etching 안 된다고 봐도 됨.


4/5 → 4/7 (4/7 필기X)

Various etching profile



- (a) Typical pyramidal pit, bounded by the (111) planes, etched into (100) silicon with an anisotropic etch through a square hole in an oxide mask.
- (b) Type of pit which is expected from an anisotropic etch with a slow convex undercut rate.
- (c) The same mask pattern can result in a substantial degree of undercutting using an etchant with a fast convex undercut rate.
- (d) Further etching of (c) produces a cantilever beam suspended over the pit.
- (e) Illustration of the general rule for anisotropic etch undercutting assuming a "sufficient time"

Convex corner compensation



- For convex corners, the **fastest etching planes dominate** the three-dimensional shape.
- For concave corners, **the slowest etching planes** dominate the three dimensional shape.
- For an arbitrary(임의의) shaped mask with transparent opening, the **pyramidal shape is bound** by the outside boundary







Mainly used anisotropic etchants


КОН	EDP	ТМАН
- High etching rate (400) - Nontoxic	- MOS process compatible (Sodium free) - Good uniformity - Abrupt stop at etching stop	- Nontoxic - MOS process compatible (Sodium free) - Will not attack the silicon doped AI - Stable (will not decompose under 130 degree C)
- Contaminate the MOS process (Potassium ion) - Temperature sensitive - Stratified etching rate	- Toxic - Low etching rate (35)	- Bad surface roughness on the bottom <100> - High undercutting ratio

EDP: Ethylenediamine pyrocatechol, TMAH: Tetramethyl ammonium hydroxide

Etch stop methods

1) Dopant dependent etch stop

- 2) Electrochemical etch stop
- 3) Timed etch stop
- 4) Etch-through window \rightarrow thickness of a commercial silicon wafer = 525 um \pm



Etching for ...


```
Etching for SiO<sub>2</sub>, Si<sub>3</sub>N<sub>4</sub>, poly-Si (a-Si), and Al
    • SiO<sub>2</sub> etching: Hydrofluoric acid (HF)
                : Buffered oxide etch (BOE or BHF)
                     HF + NH<sub>4</sub>F (ammonium fluoride)
    • Si<sub>3</sub>N<sub>4</sub> etching: HF + boiling H<sub>3</sub>PO<sub>4</sub> (phosphoric acid)
                 : BOE or BHF + boiling H<sub>3</sub>PO<sub>4</sub>
                   85% H<sub>3</sub>PO<sub>4</sub> at 180°C
                   → etching selectivity for SiO<sub>2</sub>
             ; PR has problems as etching mask
              → Using SiO<sub>2</sub> mask
    • Poly & a-Si: Same etchant of Single crystal Si
                : Etch rate is faster than SC Si
                : Almost isotropic etching
    • Al etching: 73% H<sub>3</sub>PO<sub>4</sub> + 4% HNO<sub>3</sub> (nitric acid) + 3.5% CH<sub>3</sub>COOH (acetic acid)
                     +19.5% DI water
                    : Generally, developer can etch pure Al easily

Ref: Michael Köhler "Etching in Microsystem"
                      → Al alloy can solve this problem (AlNd)
```


2) Dry Etching


Dry: Anisotropic etching

Dry etching (Plasma assisted etching)










electric field and collide with the atom shell, and neutral atom becomes positive ion

Plasma:


- 1. Initiated by free electron (such like field emission from negative biased electrode)
- 2. The electron gain kinetic energy from electrical field
- 3. The electron collide with gas molecules \rightarrow Ion + electron

Plasma:

The ionized gas composed of equal numbers of <u>positive ions</u> and <u>negative</u> <u>electrons</u> and <u>unionized molecules</u>



Sequence: mechanism




Process

- 1. The etchant species is generated by plasma
- 2. The reactant moves to the surface of substrate
- 3. The reactant is absorbed on the surface
- 4. Chemical (Physical) reaction
- 5. The compounds are detached

<Etching gas for dry method>

SOLID	ETCH GAS	ETCH PROD.
Si, SiO ₂ , Si ₃ N ₄	CF ₄ , SF ₆ , NF ₃	SiF ₄
Si	CCl ₂ , CCl ₂ F ₂	SiCl ₂ SiCl ₄
Al	BCl _{3,} CCl _{4,} SiCl _{4,} Cl ₂	AICI _{3,} AI ₂ CI _{6,}
Organic solid	O _{2,}	CO, CO _{2,} H ₂ O
	O ₂ + CF ₄	CO, CO _{2,} HF
Refractory Metal (W, Ta, Mo)	CF ₄	WF ₆ ,

Physical mode & Chemical mode



- Sputtering effect : Ion bombardment → Physical mode
- ② Pure chemical reaction → Chemical mode

<100mTorr

Physical Sputtering

Higher

Ion Sheath

 $d_{is} = 5 \text{ mm}$

Excitation Energy

(and Ion Beam Milling)

- Physical momentum transfer
- Directional etch (anisotropic) possible
- Poor selectivity
- Radiation damage possible

Reactive Ion Etching (RIE)

- Physical (ion) and Chemical
- Directional (~ anisotropic)
- More selective than sputtering


Plasma etching

- Chemical, thus faster by 10-1000x
- Isotropic
- More selective
- Less prone to radiation damage

Comparison of ion energy and operating pressure ranges for different types of plasma reactors.

Higher

Pressure




*ICP: inductively coupled plasma ECR: electron cyclotron resonance

d_{is}=0.28 mm

Anisotropic etching & High selectivity : Ultimate target
→ - Low pressure

- High plasma density with low power



<TCP: transformer coupled plasma>


<ICP>

Pressure: 5Pa


λ=1.33 mm

 $d_{is}/\lambda = 3.8$

Trench structure



Aspect ratio = $\frac{D}{W}$



High aspect ratio & Small dimension


→ Low etching rate


:limitation of ion and neutral transport in trench


New method (1): Bosch Process (Deep RIE)





: High aspect ratio trench or pillar structure \rightarrow Side wall passivation











New method (2): Atomic Layered Etch (ALE)

: self-limiting chemical modification steps -> affect only the top atomic layers of the wafer -> etching steps which remove only the chemically-modified areas, allows the removal of individual atomic layers