LINK MIDDLE EAST GENERAL CONTRACTING COMPANY

12 GOLDEN RULES

1 BEFORE WE START
ALWAYS prepare the job site, conduct a risk assessment & pre-start briefing

2 ARE WE FIT TO START?
Drugs & alcohol
NEVER work or drive under the influence

3 Protective Equipment and Tools
ALWAYS wear the appropriate PPE and use the correct tools

4 WE WORK SAFELY
Fall from height
ALWAYS put in place collective measures to prevent falls from height and falling objects. ALWAYS wear your body harness as a second measure

5 Dangerous energy
ALWAYS verify that there is no live energy (mechanical, chemical, electrical, fluids under pressure, etc.) before starting work

6 Plant, vehicles & traffic management
ALWAYS stay out of the path of moving vehicles, plant and equipment and keep eye contact with the driver

7 Lifting activities
ALWAYS keep clear of loads and lifting/moving activities. ALWAYS follow safe lifting practices

8 Confined spaces
NEVER enter a confined space unless authorised and permitted

9 Hot work, fire and explosion
NEVER perform hot work before the fire or explosion risks have been eliminated

10 Stability of excavations and structure
ALWAYS ensure trenches/excavations are secured and structures are stable

11 Health
ALWAYS ensure the environment is healthy (chemicals, dust, fumes...) and adapt the job to the person (ergonomics). ALWAYS stay focused when using hand-held devices

12 STOP! Shared vigilance!
ALWAYS stop work or stop a colleague when feeling unsafe and ask for support