Software Observation Report

OBS-061 - Alert Reset Timing

REQTRACE AI SYNTHETIC EVIDENCE

Observation ID: OBS-061
Revision: Rev01
Status: OPEN
Severity: Major
Referenced Requirement: REQ-050
Applicable FRD Revision: Not specified
Referenced Test: Not provided
Referenced File: alert_manager.c
Referenced Function: reset_alert

1. Observation Description

The observation reports that the alert indication cleared 760 milliseconds after the reset command was accepted.

2. Revision Conflict

FRD Rev01 requires clearing within 500 milliseconds.

FRD Rev02 requires clearing within 1000 milliseconds.

The observation does not identify the applicable FRD revision for the tested software baseline.

3. Assessment Constraint

A deterministic compliance conclusion is not permitted until the applicable FRD revision is established.

FICTIONAL TRAINING DATA - NOT FOR ENGINEERING APPROVAL, CERTIFICATION, SAFETY APPROVAL, AIRWORTHINESS APPROVAL, PRODUCTION RELEASE, OR OBSERVATION CLOSURE.