Progress Report Coastal Embankment Improvement Project CEIP-1 BANGLADESH FOUNDRY AND ENGINEERING WORKS Date: 01 June-2017 LTD Polder No.35/1, Sharankhola, Bagerhat Day: Thursday DAILY PROGRAM /ROGRESS REPORT Work type Location Work description To day work progress Tomorrow work Problem affecting the work program progress: Slow/Stop Embankment 0+780km to Earth fill in resectioning of Due to insufficient earth 1+100km embankment. source, earth fill progress is Structure-DS-02 6+300 km RE bar work RE bar binding in wing and return RE bar placing in wing Due to accumulated rain water wall of RS wall and return wall -RS in side the DS-2 progress of will continue work affected Concrete work in chut Concrete work in chut block done Concrete work in chut block partly in RS black in RS Structure-FS-01 0+750 km CC Block Boraitola Block machine hooper foundation Block machine hooper done partly foundation and installation conrete pump to start cc block manufacturing **Emergency protective** 3+300km to 3+380 Temporary bank protection Low progress Bullah bracing work and Placement Ibour not enough work drum/M5 sheet and sand local problem bag placing work 2+700km Temporary bank protection Fillling and placing of sand bag at the Fillling and placing of working time reduced due to river bank near broken school sand bag at the river high tide in day hour approx. 400 bag bank near broken school 2+500km Earth fill in damaged spot Earth fill in damaged spot of Earth fill in damaged spot ocal people problem of embankment embankment including sand bag of embankment including sand bag placement did not due to not placement of labour placement 2+100km progress not achieved due excavator Earth work in exavator could not proceed could not work emmergency dyke to due to yesterday night raifall achieve the design section Other: Project Manage Authorised Signature :

OVITA PROGRAM /ROGRESS REPO