ΕΘΝΙΚΟ ΜΕΤΣΟΒΙΟ ΠΟΛΥΤΕΧΝΕΙΟ

Σχολή Ηλεκτρολόγων Μηχανικών & Μηχανικών Υπολογιστών

ΣΥΣΤΗΜΑΤΑ ΜΙΚΡΟΫΠΟΛΟΓΙΣΤΩΝ ΤΡΙΤΗ ΟΜΑΔΑ ΑΣΚΗΣΕΩΝ

Ναταλία Μπούρδη

AM: <u>el19031</u>

Ανδρέας Παπαθανασίου

AM: <u>el19212</u>

ΤΟ ΠΡΟΓΡΑΜΜΑ ΤΗΣ ΑΣΚΗΣΗΣ – ΚΩΔΙΚΑΣ ASSEMBLY:

```
IN 10H
LXI B,000AH ; 10ms delay
MVI E,00H
MVI A,1DH
            ; Άρχικοποίηση διακοπών
SIM ;
ΕI
LOOP1:
MVI A, FFH ; LEDs OFF
STA 3000H
JMP LOOP1
INTR ROUTINE:
MVI D,2EH
               ; Μετρητης αλλαγων καταστασης των LEDs (2D=45)
REPEAT:
CALL BLINK
CALL PRINT
CALL DELB
CALL BLINK
CALL DELB
DCR D
JZ END
JMP REPEAT
END:
MVI A,1DH ; Αρχικοποίηση διακοπών
SIM
ΕI
RET
BLINK:
                ; Αλλαγη καταστασης των LEDs
MOV A,E
STA 3000H
CMA
MOV E,A
RET
DELB :
               ; 500ms delay με ανανεωση των 7-segment displays καθε
10msec
MVI A,32H
               ; 50x10msec delays
DELB LOOP:
CALL DELB
```

```
CALL DCD
DCR A
JNZ DELB_LOOP
RET
```

MVI M, 10H

PRINT: ;εμφανιζουμε το περιεχομενο του καταχωρητη D στα δυο 7segment displays CALL SPACES LXI H,0905H ;δειυθυνση που θα γραφούν τα συμβολα προς απεικονιση PUSH B PUSH D MVI B,00H ;Κραταει δεκαδες MVI C,00H ;Κραταει μοναδες CONVERT: DCR D **;Μειωνουμε τον** D JZ CONT CALL DEC ; Αυξανουμε το ζευγος Β, С JMP CONVERT DEC : ;Σε καθε επαναληψη αφαιρουμε 1 απο τον D INR C ; και προσθετουμε 1 στο ζευγος Β, C σε δεκαδικη αναπαρασταση MOV A,C CPI OAH JNZ RET_ INR B MVI C,00H RET : RET CONT: MOV M,B ;store B to memory DCX H ;move pointer to the other address MOV M,C ;Διευθυνση μνημης από όπου θα διαβασουν οι STDM και DCD LXI D,0900H CALL STDM CALL DCD ;απεικονιση με χρηση των STDM, DCD POP D POP B RET SPACES: ; Άρχικοποιηση με κενα στα ψηφια που θα τυπωνονται LXI H,0900H ;χρησιμοποιουμε τη διευθυνση 0900Η MVI M,10H INX H MVI M, 10H INX H MVI M,10H INX H MVI M, 10H INX H

```
INX H
MVI M,10H
RET
```

Το Προγραμμα της Ασκήσης – Κωδικάς Assembly:

```
IN 10H
                 ; empty character code
MVI A,10H
STA OBOOH
STA OBO1H
STA 0B02H
                 ; will place low digit here
STA OBO3H
                 ; high digit
STA 0B04H
STA 0B05H
MVI A,1DH
SIM
ΕI
MVI C,40H
              ; 64 DEC
                 ; 128 DEC
MVI D,80H
                 ; 192 DEC
MVI E, COH
LOOP1:
    ;CALL DCD
    JMP LOOP1
INTR ROUTINE:
   PUSH B
                ; saving register values...
    PUSH D
              ; will place low digit here
    STA 0B02H
    STA 0B03H
                 ; will place high digit here
   LXI D,0B00H
   CALL STDM
   CALL KIND
                 ; A <- digit pressed (high)
   ANI OFH
    STA 0B03H ; placing high digit for displaying later
   RLC
   RLC
   RLC
   RLC
   MOV H,A
                 ; A <- digit pressed (low)
   CALL KIND
   ANI OFH
              ; placing low digit for displaying later
    STA 0B02H
   ORA H
                  ; A now has both digits
```

```
LEDS:
    POP D
    POP B
                 ; restoring C,D,E values to check for the LEDs
    CMP E
    JZ LED2
    CMP E
    JNC LED3
    CMP D
    JZ LED1
    CMP D
    JNC LED2
    CMP C
    JZ LED0
    CMP C
    JNC LED1
    JMP LED0
LED0:
   MVI A, FEH
    STA 3000H
    JMP EXIT
LED3:
    MVI A, F7H
    STA 3000H
    JMP EXIT
LED1:
   MVI A, FDH
    STA 3000H
    JMP EXIT
LED2:
   MVI A, FBH
    STA 3000H
    JMP EXIT
DELB_: ;~500ms delay με ανανεωση των 7-segment displays καθε 10msec
   MVI A,32H
                       ;50x10msec delays
    DELB LOOP:
    CALL DELB
    CALL DCD
    DCR A
    JNZ DELB_LOOP
    RET
EXIT:
    PUSH D
    PUSH B
                 ; saving registers again...
    LXI D,0B00H ; for STDM
    CALL STDM
    CALL DCD
                  ; 10msec delay for DELB (see DELB for the final delay
    LXI B,000AH
duration)
    CALL DELB_
                  ; to view leds
```

```
MVI A,FFH ; reset leds
STA 3000H
POP B
POP D ; restore registers...

MVI A,1DH ; initialize interrupts
SIM
EI
RET
END
```

```
A.
INR16 MACRO ADDR
     PUSH H
              ; Αποθηκευουμε τους Η, L στη στοιβα
     LXI H, ADDR ; H, L<-ADDR
     MOV M, A
              ; A<-(ADDR)
     ADI 01H
                ; Αυξανουμε το Xlow.
                 ; Το CY γινεται 1 σε περιπτωση υπερχειλισης
               ; (ADDR) <-A
     MOV M, A
     INX H
               ; Αυξανουμε την τιμη του ζευγους Η, L
     MOV A,M
               ; A<-(ADDR+1)
     ACI 00H
               ; Προσθετουμε στο Xhigh το κρατουμενο σε
                ; περιπτωση υπερχειλισης
     MOV M, A
                ; (ADDR+1)<-A
     POP H
                ; Επαναφέρουμε τους καταχωρητές Η, L
     ENDM
В.
FILL MACRO ADDR,K
     LXI H, ADDR ; H, L<-ADDR
     MVI A,K
              ; A<-K
     REPEAT:
     MOV M, A
              ; ((H),(L))<-A
     INX H
               ; Αυξανουμε την τιμη του ζευγους Η, L
              ; Μειωνουμε την τιμη του Α
     JNZ REPEAT ; Av A=0 \tau \epsilon \lambda o \varsigma
     ENDM
```

Γ.

RHLL MACRO Q,R

```
MOV A,R RAL ; Περιστροφή του R αριστερα μεσω κρατουμένου MOV R,A ; RO<-CY και CY<-R7 MOV A,Q RAL ; Περιστροφή του Q αριστέρα μέσω κρατουμένου MOV Q,A ; QO<-R7 και CY<-Q7 ENDM
```

Όταν αναγνωριστεί διακοπή από τον μΕ αρχικά ολοκληρώνεται η εκτέλεση της τρέχουσας εντολής, έπειτα σώζεται στη στοίβα ο PC και τέλος ο PC λαμβάνει τη διεύθυνση της διακοπής που αναγνωρίστηκε. Η ρουτίνα εξυπηρέτησης που θα κληθεί από τη διεύθυνση αυτή θα αναλάβει να σώσει την κατάσταση του μΕ και τους καταχωρητές που θα χρησιμοποιήσει.

	Λειτουργίες του μΕ	Περιγραφή	
ЈМР 2200Н	PC<-2200H	Η εντολή JMP εκτελείται μέχρι το τέλος, άρα PC<- 2200Η	
RST6.5:	(SP-1) <-PCH (SP-2) <-PCL	(2FFFH) <-22H (2FFEH) <-00H	
	SP<-SP-2	SP<-2FFEH	
	PC<-0034H	PC<-0034Η (Η διεύθυνση της διακοπής RST6.5)	
Εκτέλεση ρουτίνας εξυπηρέτησης…			
Επιστροφή από τη ρουτίνα εξυπηρέτησης	PCL<-(SP) PCH<-(SP+1) SP<-SP+2	PCL<-00H PCH<-22H SP<-3000H	

Αμέσως πριν την κλήση της ρουτίνας εξυπηρέτησης της διακοπής έχουμε:

PC	SP	Διεύθυνση	Περιεχόμενο
2200Н	3000н	2FFFH	22Н
		2FFEH	00н

Στις διευθύνσεις 2FFFH, 2FFEH εξακολουθούν μετά την εκτέλεση της ρουτίνας εξυπηρέτησης της διακοπής και της επαναφοράς του stack pointer να υπάρχουν οι τιμές 22H και 00H αντίστοιχα. Όμως, επειδή η στοίβα μεγαλώνει προς τα κάτω οι παραπάνω διευθύνσεις δεν ανήκουν στην στοίβα. Επομένως, τα περιεχόμενά της είναι τα ίδια με αυτά που ήταν πριν την διακοπή.

ΆΣΚΗΣΗ 5

```
A.
; Initialize registers
MVI B,00H
              ; Overflow counter
MVI C,00H
               ; Sum of the inputs
MVI E,20H
               ; Counter for the 32 reads
LXI H,9000H
LOOP:
JMP LOOP
                ; Wait for interrupts
RST5.5:
               ; Interrupt routine
     IN 20H
               ; Read 4 digits from the device
     MOV M,A
              ; Store them in memory
     INX H
               ; Increase the address
     DCR E
               ; Decrement counter
     JZ EXIT
              ; Exit if all data is read
     RET
                ; Else return
EXIT:
LXI H,9000H
                ; Restore to the initial address
MVI E,10H
                ; Counter for the 16 numbers to be summed
SUM:
     MOV A, M
                ; Read 4 LSBs from memory
     RRC
     RRC
     RRC
```

```
RRC
                ; put LSBs in the correct position
     MOV D,A ; Store them temporarily
     INX H
              ; Increase memory address
     MOV A,M ; Read 4 MSBs from memory
     INX H ; Increase memory address
     ORA D
              ; Now A has the whole number
     ADD C
               ; Add to the sum
     JNC CONT ; If there is overflow increment B
     INR B
CONT:
     MOV C,A ; Store the sum in C
     DCR E
     JNZ SUM ; If all 16 numbers are summed, continue
; The sum is now stored in the B,C register pair
; We need to divide it by 16
STC
CMC
          ; Clear carry
MVI E,04H ; 4 right rotations needed to divide the sum by 16
DIVIDE:
     MOV A,B
     RAR
              ; Rotate B through carry
     MOV B,A
     MOV A,C
              ; Rotate C through carry
     RAR
     MOV C,A
               ; Now the value stored in B,C is divided by 2
     DCR E
     JNZ DIVIDE
MOV A,C
               ; Now A has the result!
RET
                ; To return from the interrupt routine
В.
; Initialize registers
MVI B,00H ; Overflow counter MVI C,00H ; Sum of the inputs
MVI E,20H
              ; Counter for the 32 reads
LXI H,9000H
LOOP:
```

IN 20H

```
MOV B, A
ANI 01H
              ; Wait for 'DATA READY' to become 0
JNZ LOOP
DATA READY:
     MOV M,B ; Store them in memory
     INX H
              ; Increase the address
              ; Decrement counter
     DCR E
     JZ EXIT
              ; Exit if all data is read
WAIT FOR 1:
     IN 20H
     ANI 01H
     JZ WAIT FOR 1 ; Wait for 'DATA READY' to return to 1
     JMP LOOP
                    ; When 'DATA READY' = 1 return
EXIT:
LXI H,9000H
                     ; Restore to the initial address
MVI E,10H ; Counter for the 16 numbers to be summed
SUM:
     MOV A,M ; Read 4 LSBs from memory
     RRC
     RRC
     RRC
     RRC
              ; put LSBs in the correct position
     MOV D,A
               ; Store them temporarily
     MOV A,M ; Read 4 MSBs from memory
     ANI FOH ; Clear 'data ready' bit
     INX H ; Increase memory address
ORA D ; Now A has the whole number
ADD C ; Add to the sum
     JNC CONT ; If there is overflow increment B
     INR B
CONT:
     MOV C,A ; Store the sum in C
     DCR E
     JNZ SUM ; If all 16 numbers are summed, continue
; The sum is now stored in the B,C register pair
; We need to divide it by 16
STC
          ; Clear carry
MVI E,04H ; 4 right rotations needed to divide the sum by 16
DIVIDE:
     MOV A,B
     RAR
               ; Rotate B through carry
     MOV B,A
     MOV A,C
```

RAR ; Rotate C through carry
MOV C,A ; Now the value stored in B,C is divided by 2

DCR E

JNZ DIVIDE

MOV A,C ; Now A has the result!