
System Dynamics and Control 1 Root Locus Technic

Root Locus Techniques





HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

Root Locus Techniqu

Learning Outcome

After completing this chapter, the student will be able to

- · Define a root locus
- · State the properties of a root locus
- · Sketch a root locus
- Find the coordinates of points on the root locus and their associated gains
- Use the root locus to design a parameter value to meet a transient response specification for systems of order 2 and higher
- Sketch the root locus for positive-feedback systems
- · Find the root sensitivity for points along the root locus

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

3

Root Locus Techniques

§1. Introduction

Root Locus Technique was discovered by Evans in 1948

The Control System Problem



 $R(s) = \begin{bmatrix} KG(s) & C(s) \\ 1 + KG(s)H(s) \end{bmatrix}$

Closed-loop system $\text{Closed-loop TF:} \quad T(s) = \frac{KG(s)}{1 + KG(s)H(s)}$

Equivalent transfer function

Open-loop TF: KG(s)H(s)

- From open-loop TF KG(s)H(s)
- can determine the poles of KG(s)H(s)
- variations in *K* do not affect the location of any pole of this TF
- From the closed-loop TF T(s)
- cannot determine the poles of T(s) unless factor the denominator
- the poles of T(s) change with K

HCM City Univ. of Technology, Faculty of Mechanical Engineering


Nguyen Tan Tien

System Dynamics and Control

Root Locus Techniques

§1. Introduction

The Control System Problem



 $\frac{KG(s)}{1 + KG(s)H(s)} \stackrel{C(s)}{\longrightarrow}$

Closed-loop system $\text{Closed-loop TF:} \quad T(s) = \frac{KG(s)}{1 + KG(s)H(s)}$

Equivalent transfer function Open-loop TF: KG(s)H(s)

- The poles of T(s) are a function of $K \to \text{find}$ the poles for specific values of K to estimate the system's transient response and

stability

- The root-locus method displays the location of the poles of the closed-loop TF as a function of the gain factor *K* of the open-loop TF

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

5 Root Locus Techniqu

§1. Introduction

Vector Representation of Complex Numbers



Any complex number, $s = \sigma + j\omega$, described in Cartesian coordinates can be graphically represented σ by a vector or in polar form $M \angle \theta$



If F(s)=(s+a) then substituting the complex number $s=\sigma+j\omega$ yields $F(s)=(\sigma+a)+j\omega$, $-\frac{\pi}{a}$ another complex number



F(s) has a zero at -a. If translate the vector a units to the left \rightarrow alternate representation of the complex number that originates at the zero -a and terminates on the point $s=\sigma+j\omega$

ightarrow s + a is a complex number and can be represented by a vector drawn from the zero of the function to the point s

System Dynamics and Control

Root Locus Techniques

§1.Introduction

 \rightarrow s+a is a complex number and can be represented by a vector drawn from the zero of the function to the point s

 $\underline{\mathsf{Ex}}_{\cdot}(s+7)|_{s\to 5+j2}$ is a complex number drawn from the zero of the function, -7, to the point s, which is 5+j2



HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§1. Introduction

Apply the concepts to a complicated function

$$F(s) = \frac{\prod_{i=1}^{m}(s+z_i)}{\prod_{j=1}^{n}(s+p_j)} = \frac{\prod \text{numerator's complex factors}}{\prod \text{denominator's complex factors}} \quad (8.4)$$

The function defines the complex arithmetic to be performed in order to evaluate F(s) at any point, s

Since each complex factor can be thought of as a vector

• the magnitude, M, of F(s)

$$M = \frac{\prod \text{zero lengths}}{\prod \text{pole lengths}} = \frac{\prod_{i=1}^{m} |(s+z_i)|}{\prod_{j=1}^{n} |(s+p_j)|}$$
(8.5)

• the angular, θ , of F(s)

$$\theta = \Sigma$$
zero angles – Σ pole angles

$$= \sum_{i=1}^{m} \angle(s + z_i) - \sum_{j=1}^{n} \angle(s + p_j)$$
 (8.6)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien


System Dynamics and Control §1. Introduction

- Ex.8.1

Evaluation of a complex function via vectors

Given
$$F(s) = \frac{s+1}{s(s+2)}$$
. Find $F(s)$ at the point $s = -3 + j4$

Solution



HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nouven Tan Tien

System Dynamics and Control

Root Locus Techniques

§1. Introduction

Skill-Assessment Ex.8.1

Problem Given

$$F(s) = \frac{(s+2)(s+4)}{s(s+3)(s+6)}$$

Find F(s) at the point s = -7 + j9 the following ways

a. Directly substituting the point into F(s)

b. Calculating the result using vectors

Solution a. Directly substituting the point into F(s)

$$F(-7+j9) = \frac{(-7+j9+2)(-7+j9+4)}{(-7+j9)(-7+j9+3)(-7+j9+6)}$$

$$= \frac{(-5+j9)(-3+j9)}{(-7+j9)(-7+j9)(-1+j9)}$$

$$= \frac{-66-j72}{944-j378} = -0.0339-j0.0899$$

$$= 0.0962-110.7^{0}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering


Nguyen Tan Tien

System Dynamics and Control

Root Locus Techniques

§1. Introduction

b. Calculating the result using vectors



HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nauven Tan Tien

System Dynamics and Control

§1. Introduction

Trylt 8.1 Use the following MATLAB statements to solve the problem given in Skill-Assessment Ex.8.1. s=-7+9i: G=(s+2)*(s+4)/.. (s*(s+3)*(s+6)); Theta=(180/pi)*angle(G) M=abs(G)

$$G(s) = \frac{(s+2)(s+4)}{s(s+3)(s+6)}$$

-110.6881 0.0961

System Dynamics and Control

Root Locus Techniques

§2. Defining the Root Locus



Security cameras with auto tracking can be used to follow moving objects automatically



- The variation of pole location for different values of gain, K


									0 ,				
K	0	5	10	15	20	25	30	35	40	45	50		
							-5 + j2.24						
pole 2	-10	-0.53	-1.13	-1.84	-2.77	-5	-5 - j2.24	-5 - j3.16	-5 - j3.87	-5 - j4.47	-5 - j5		

HCM City Univ. of Technology, Faculty of Mechanical Engineering

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§2. Defining the Root Locus

- root locus: the paths of the closed-loop poles as the gain K is



-0.53 -1.13 -1.84 -2.77 -5 -5 - i2.24 -5 - i3.16 -5 - i3.87 -5 - i4.47

HCM City Univ. of Technology, Faculty of Mechanical Engineering

System Dynamics and Control

§3. Properties of the Root Locus

- The closed-loop TF for the system

$$T(s) = \frac{KG(s)}{1 + KG(s)H(s)}$$
(8.12)

- The pole, s, is the roots of the characteristics equation

$$\begin{split} KG(s)H(s) &= -1 \\ &= 1 \angle (2k+1)180^0 \quad k = 0, \pm 1, \ldots \end{split}$$

or value of s is a closed-loop pole if

$$|KG(s)H(s)| = 1 \tag{8.14}$$

and
$$\angle KG(s)H(s) = (2k+1)180^{0}$$
 (8.15)

$$K = \frac{1}{|G(s)||H(s)|} \tag{8.16}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nouven Tan Tien

(8.13)

System Dynamics and Control

Root Locus Techniques

§3. Properties of the Root Locus





The pole location varies with K

$$KG(s)H(s) = \frac{K}{s(s+10)}$$


$$K = 5$$
, $p = -9.47$: $KG(s)H(s) = \frac{5}{(-9.47)(-9.47 + 10)} = -1$

$$K = 5$$
, $p = -0.53$: $KG(s)H(s) = \frac{5}{(-0.53)(-0.53 + 10)} = -1$

$$K = 10, p = -8.87$$
: $KG(s)H(s) = \frac{10}{(-8.87)(-8.87 + 10)} = -1$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nauven Tan Tien



The open-loop and closed-loop TF

$$KG(s)H(s) = \frac{K(s+3)(s+4)}{(s+1)(s+2)}$$

$$T(s) = \frac{K(s+3)(s+4)}{(1+K)s^2 + (3+7K)s + (2+12K)}$$
(8.18)

$$T(s) = \frac{K(s+3)(s+4)}{(1+K)s^2 + (3+7K)s + (2+12K)}$$
(8.19)

Consider the point -2 + j3

If this point is a closed-loop pole, then the angles of the zeros minus the angles of the poles must equal an odd multiple of 1800 $\theta_1 + \theta_2 - \theta_3 - \theta_4 = 56.31^0 + 71.57^0 - 90^0 - 108.43^0 = -70.55^0$ \rightarrow -2 + j3 is not a point on the root locus, or alternatively, -2 + j3 is not a closed-loop pole for any gain

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control §3. Properties of the Root Locus

Consider the point $-2 + j \frac{\sqrt{2}}{2}$

$$\begin{split} & \sum_{1}^{n} \theta_{z_{i}} - \sum_{1}^{m} \theta_{p_{i}} = (2k+1)180^{0} \\ & \rightarrow \theta_{1} + \theta_{2} - \theta_{3} - \theta_{4} = 180^{0} \end{split} \tag{8.20}$$

 $\rightarrow -2 + j\frac{\sqrt{2}}{2}$ is a point on the root locus for some value of gain K

The gain *K* for the point $-2 + j(\sqrt{2}/2)$

$$K = \frac{1}{|G(s)||H(s)|} = \frac{1}{M} = \frac{\prod \text{pole lengths}}{\prod \text{zero lengths}}$$

$$\to K = \frac{\vec{L}_3 \vec{L}_4}{\vec{L}_1 \vec{L}_2} = \frac{(\sqrt{2}/2) \times 1.22}{2.12 \times 1.22} = 0.33$$
(8.21)

Nguyen Tan Tien

System Dynamics and Control

§3. Properties of the Root Locus

Skill-Assessment Ex.8.2

Problem Given a unity feedback system that has the forward TF


$$G(s) = \frac{K(s+2)}{(s^2+4s+13)}$$

- a. Calculate the angle of G(s) at the point (-3 + j0) by finding the algebraic sum of angles of the vectors drawn from the zeros and poles of G(s) to the given point
- b. Determine if the point specified in a is on the root locus
- c. If the point specified in a is on the root locus, find the gain, K, using the lengths of the vectors

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§3. Properties of the Root Locus

Solution a.Directly substituting the point into F(s)



b. Since the angle is 180° , the point (-3+j0) is on the locus pole lengths

$$c.K = \frac{\text{II pole lengths}}{\text{II zero lengths}}$$
$$= \frac{\sqrt{1^2 + 3^2} \times \sqrt{1^2 + 3^2}}{1} = 10$$

HCM City Univ. of Technology. Faculty of Mechanical Engineering

System Dynamics and Control

Root Locus Techniques

§3. Properties of the Root Locus

Trylt 8.2

Use MATLAB and the following statements to solve Skill-Assessment Ex.8.2 s=-3+0i: G=(s+2)/(s^2+4*s+13); Theta=(180/pi)*angle(G) M=abs(G); K=1/M

$$G(s) = \frac{(s+2)(s+4)}{s(s+3)(s+6)}$$

G=(s+2)*(s^2+4*s+13); Theta=(180/pi)*angle(G) M=abs(G)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguven Tan Tien

System Dynamics and Control

Root Locus Techniques

§4. Sketching the Root Locus

The following five rules allow us to sketch the root locus

1. Number of branches

The number of branches of the root locus equals the number of closed-loop poles

2.Symmetry

The root locus is symmetrical about the real axis

3.Real-axis segments

On the real axis, for K > 0 the root locus exists to the left of an odd number of real-axis, finite open-loop poles and/or finite open-loop zeros



HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nauven Tan Tien

System Dynamics and Control

Root Locus Techniques

§4. Sketching the Root Locus

4. Starting and ending points

The root locus begins at the finite and infinite poles of G(s)H(s) and ends at the finite and infinite zeros of G(s)H(s)

$$T(s) = \frac{KG(s)}{1 + KG(s)H(s)} = \frac{K\frac{N_C(s)}{D_C(s)}}{1 + K\frac{N_C(s)}{D_G(s)}\frac{N_H(s)}{D_H(s)}} = \frac{KN_G(s)}{D_G(s)D_H(s) + KN_G(s)N_H(s)}$$

$$K \rightarrow 0 \colon T(s) = \frac{KN_G(s)}{D_G(s)D_H(s) + KN_G(s)N_H(s)} \approx \frac{KN_G(s)}{D_G(s)D_H(s) + \epsilon}$$

→ the closed-loop system poles at small gains approach the combined poles of ${\it G(s)}$ and ${\it H(s)}$: the root locus begins at the poles of ${\it G(s)H(s)}$, the open-loop TF

$$K \rightarrow \infty : T(s) = \frac{KN_G(s)}{D_G(s)D_H(s) + KN_G(s)N_H(s)} \approx \frac{KN_G(s)}{\epsilon + KN_G(s)N_H(s)}$$

 \rightarrow the closed-loop system poles at large gains approach the combined zeros of G(s)and H(s): the root locus ends at the zeros of G(s)H(s), the open-loop TF

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§4. Sketching the Root Locus

5. Behavior at infinity

The root locus approaches straight lines as asymptotes as the locus approaches infinity. Further, the equation of the asymptotes is given by the real-axis intercept, σ_a and angle, θ_a as follows finite poles

$$\sigma_a = \frac{\sum \text{finite poles} - \sum \text{finite zeros}}{\# \text{ finite poles} - \# \text{ finite zeros}} = \frac{\sum_{1}^{n} p_i - \sum_{1}^{m} z_i}{n - m}$$
(8.27)

$$\theta_a = \frac{(2k+1)\pi}{\# \text{ finite poles-} \# \text{ finite zeros}} = \frac{n-m}{n-m}$$
(8.28)

where $k = 0, \pm 1, \pm 2, ...$ and the angle is given in radians with respect to the positive extension of the real axis

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§4. Sketching the Root Locus

Sketching a root locus with asymptotes

Sketch the root locus for the system

K(s+3) s(s+1)(s+2)(s+4)

Solution Find the asymptotes

The real-axis intercept

The angles of line that intersect at -4/3 $\theta_a = \frac{(2k+1)\pi}{m-n} = \frac{(2k+1)\pi}{4-1} = \frac{(2k+1)\pi}{3}$ $\rightarrow \theta_a = (k, \theta_a) = [(0; \pi/3), (1; \pi), (2; 5\pi/3)]$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§4. Sketching the Root Locus

Skill-Assessment Ex.8.3

Problem Sketch the root locus and its asymptotes for a unity feedback system that has the forward TF

$$G(s) = \frac{K}{(s+2)(s+4)(s+6)}$$

Solution Find the asymptotes



The real-axis intercept

$$\sigma_a = \frac{\sum_{1}^{m} p_i - \sum_{1}^{n} z_i}{m - n} = \frac{(-2 - 4 - 6) - (0)}{3 - 0} = -4$$

The angles of line that intersect at -4

$$\theta_a = \frac{(2k+1)\pi}{m-n} = \frac{(2k+1)\pi}{3-0} = \frac{(2k+1)\pi}{3}$$

$$\to \theta_a = (k,\theta_a) = [(0;\pi/3),(1;\pi),(2;5\pi/3)]$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nouven Tan Tien

System Dynamics and Control

§5. Refining the Sketch Real-Axis Breakaway and Break-In Points



breakaway point: $-\sigma_1$ break-in point: σ_2

At the breakaway or break-in point, the branches of the root locus form an angle of $180^{0}/n$ with the real axis

n: the number of closed-loop poles arriving at or departing from the single breakaway or break-in point on the real axis (Kuo, 1991) For the two poles shown, the branches at the breakaway point form $180^{\circ}/n = 180^{\circ}/2 = 90^{\circ}$ angles with the real axis

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nouven Tan Tien

System Dynamics and Control

Root Locus Techniques

§5. Refining the Sketch

• Find breakaway and break-in point by maximize/minimize the gain



Eq. (8.13)
$$\rightarrow K = -\frac{1}{G(s)H(s)}$$
 (8.31)

Along the real axis Eq. (8.31) becomes
$$K = -\frac{1}{G(\sigma)H(\sigma)}$$
 (8.32)

To find breakaway and break-in point → differentiate (8.32) with respect to σ and set the derivative equal to zero

$$KG(s)H(s) = -1 = 1\angle(2k+1)180^{0} \quad k = 0,\pm 1, ...$$

(8.13)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

Ex.8.3

Root Locus Techniques

§5. Refining the Sketch

Breakaway and break-in points via differentiation

Find the breakaway and break-in points for the root locus of the given figure, using differential calculus Using the open-loop poles and zeros

 $KG(s)H(s) = \frac{K(s-3)(s-5)}{(s+1)(s+2)} = \frac{K(s^2-8s+15)}{s^2+3s+2}$

For all points along the real axis, $KG(\sigma)H(\sigma) = -1$

$$\frac{K(\sigma^2 - 8\sigma + 15)}{\sigma^2 + 3\sigma + 2} = -1 \to K = -\frac{\sigma^2 + 3\sigma + 2}{\sigma^2 - 8\sigma + 15} \to \frac{dK}{d\sigma} = \frac{11\sigma^2 - 26\sigma - 61}{(\sigma^2 - 8\sigma + 15)^2}$$

Setting the derivative equal to zero yields

$$\frac{dK}{d\sigma}=0 \rightarrow \sigma=[-1.4530,3.8166] \rightarrow \sigma_1=-1.4530,\,\sigma_2=3.8166$$
 HCM City Unix of Technology, Faculty of Mechanical Engineering Nguyen Tan Tien

System Dynamics and Control

§5. Refining the Sketch

· Find breakaway and break-in point using transition method Breakaway and break-in points satisfy the relationship

$$\sum_{1}^{m} \frac{1}{\sigma + z_{i}} = \sum_{1}^{n} \frac{1}{\sigma + p_{i}}$$
 (8.37)

 z_i, p_i : the negative of the zero and pole values, respectively, of $G(\sigma)H(\sigma)$

Solving (8.37) for σ , the real-axis values that minimize or maximize K, yields the breakaway and break-in points without differentiating

 $KG(s)H(s) = -1 = 1\angle(2k+1)180^{0} \quad k = 0,\pm 1,...$ HCM City Univ. of Technology, Faculty of Mechanical Engineering

(8.13)Nguyen Tan Tien System Dynamics and Control

§5. Refining the Sketch

Ex.8.4 Breakaway and break-in points without differentiation

Solution Using (8.37)

Find the breakaway and break-in points for the root locus of the given figure, without differentiating

 $\frac{1}{3} + \frac{1}{3} + \frac{1}{3} = \frac{1}{3+1} + \frac{1}{3+2}$

Simplifying

$$11\sigma^2 - 26\sigma - 61 = 0$$

$$\rightarrow (\sigma + 1.4530)(\sigma - 3.8166) = 0$$

$$\rightarrow \sigma_1 = -1.4530, \sigma_2 = 3.8166$$

 $\sum_1^m \frac{1}{\sigma + z_i} = \sum_1^n \frac{1}{\sigma + p_i}$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

(8.37)Nguyen Tan Tien

Root Locus Techniques

§5. Refining the Sketch

The $j\omega$ -Axis Crossings

Use the Routh-Hurwitz criterion to find the $j\omega$ -axis crossing as follows


- 1. Forcing a row of zeros in the Routh table will yield the gain
- 2. Going back one row to the even polynomial equation and solving for the roots yields the frequency at the imaginaryaxis crossing

System Dynamics and Control

§5. Refining the Sketch

- Ex.8.5

Frequency and gain at imaginary-axis crossing



For the given system, find the frequency and gain, K, for which the root locus crosses the imaginary axis. For what range of K is the system stable?

Solution

The closed-loop transfer function for the system

$$T(s) = \frac{G(s)}{1 + G(s)}$$

$$= \frac{K(s+3)}{s^4 + 7s^3 + 14s^2 + (8+K)s + 3K}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

Root Locus Techniques

§5. Refining the Sketch

$$T(s) = \frac{K(s+3)}{s^4 + 7s^3 + 14s^2 + (8+K)s + 3K}$$

$$\frac{s^4}{s^3} \frac{1}{7} \frac{14}{K+8} \frac{3K}{0}$$

$$\frac{s^2}{s^2} \frac{-K+90}{-K+90} \frac{21K}{0} \frac{0}{0}$$

$$\frac{s^4}{s^6} \frac{-K^2 - 65K + 720}{-K+90} \frac{0}{0} \frac{0}{0}$$

Complete row of zeros → the possibility for imaginary axis roots s^1 :- K^2 - 65K + 720 = (K + 74.65)(K - 9.65) = 0

$$\rightarrow K = 9.65$$

Forming the even polynomial by using the s^2 row with K = 9.65 s^2 :(90 - K) s^2 + 21K = 80.35 s^2 + 202.7 = 0

$$\rightarrow s = \pm i1.59$$

The system is stable for $0 \le K \le 9.65$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien


System Dynamics and Control

Root Locus Techniques

§5. Refining the Sketch

Angles of Departure and Arrival

Assume a point on the root locus ϵ close to a complex pole/zero, \rightarrow sum of angles drawn from all finite poles and zeros to this point is an odd multiple of 1800



 $-\theta_1 + \theta_2 + \theta_3 - \theta_4 - \theta_5 + \theta_6 =$ $(2k + 1)180^0 \rightarrow \theta_2$

b. angle of arrival

Open-loop poles and zeros and calculation

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

Root Locus Techniques

§5. Refining the Sketch

Angle of departure from a complex pole

Find the angle of departure from the complex poles and sketch the root locus R(s)

K(s+2) $(s+3)(s^2+2s+2)$

Solution



Calculate the sum of angles draw to a point ϵ close to the complex pole, -1 + i1, in the second quadrant

$$-\theta_1 - \theta_2 + \theta_3 - \theta_4 = -\theta_1 - 90^0 + \tan^{-1}\left(\frac{1}{1}\right) + \tan^{-1}\left(\frac{1}{2}\right)$$

$$= 180^{0}$$

$$\rightarrow \theta_1 = -251.6^{0} = 108.4^{0}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

Root Locus Techniques

§5. Refining the Sketch

Plotting and Calibrating the Root Locus

Find the exact point at which the locus crosses the ζ damping ratio line and the gain at that point



 $= r_{min} : dr : r_{max}, n = length(r_{range})$ [r,k] = rlocus(sys), m = length(r)for i = 1: mfor j = 1: n $\theta(i) = \sum \theta_{z_i} - \sum \theta_{p_i}$ $\theta(i) = 180 \times |1 - |\theta(i)/\pi||$ and $[n] = \min[e]$

- using (8.20) to search a given line for the point
- using (8.21) to calculate the gain at that point

 $\overline{\Sigma^n_1} \overline{\theta_{z_i} - \Sigma^m_1 \, \theta_{p_i} = (2k+1)180^0}$ (8.20) $K = \frac{1}{|G(s)||H(s)|} = \frac{1}{M} = \frac{\prod \text{pole lengths}}{\prod \text{zero lengths}}$ (8.21)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§5. Refining the Sketch

Plotting and Calibrating the Root Locus

Ex.: Given the root locus \rightarrow Find the exact point at which the locus crosses the $\zeta = 0.45$ damping ratio line and the gain at that point



The point r on the ζ line is on the root locus if

e point
$$r$$
 on the ζ line is on the root locus if
$$(2k+1)180^0 = \theta_5 - \theta_1 - \theta_2 - \theta_3 - \theta_4 \\ = \tan^{-1}\frac{r\sin z}{|3-r\zeta|} - (180^0 - \cos^{-1}\zeta) - \tan^{-1}\frac{r\sin z}{|4-r\zeta|} \\ -\tan^{-1}\frac{r\sin z}{|2-r\zeta|} - \tan^{-1}\frac{r\sin z}{|1-r\zeta|}$$
 Nguyen 'Bin Tien' Nguyen 'Bin Tien'

HCM City Univ. of Technology, Faculty of Mechanical Engineerin

System Dynamics and Control

§5. Refining the Sketch

Plotting and Calibrating the Root Locus

Ex.: Given the root locus \rightarrow Find the exact point at which the locus crosses the $\zeta = 0.45$ damping ratio line and the gain at that point



The gain K at r = 0.7470

$$K = \frac{|r_1||r_2||r_3||r_4|}{|r_5|} = \frac{0.7471 \times 3.7241 \times 1.7926 \times 0.9412}{2.7461}$$

$$\rightarrow K = 1.7090$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nouven Tan Tien

System Dynamics and Control

Root Locus Techniques

§5. Refining the Sketch

Skill-Assessment Ex.8.4

Problem Given a unity feedback system that has the forward TF

$$G(s) = \frac{K(s+2)}{s^2 - 4s + 13}$$

- do the following
- a. Sketch the root locus
- b. Find the imaginary-axis crossing
- c. Find the gain, K, at the $i\omega$ -axis crossing
- d. Find the break-in point
- e. Find the angle of departure from the complex poles

System Dynamics and Control

Root Locus Techniques

§5. Refining the Sketch

Solution a. The sketched root locus

$$G(s) = \frac{K(s+2)}{s^2 - 4s + 13}$$

b.The imaginary-axis crossing
$$T(s) = \frac{G(s)}{1 + G(s)} = \frac{K(s+2)}{s^2 - (K-4)s + (2K+13)}$$

The Routh table

from row of zero $\rightarrow K = 4$

from
$$s^2$$
 row with $K = 4 \rightarrow s^2 + 21 = 0 \rightarrow s = \pm i\sqrt{21}$

c. The gain, K, at the $j\omega$ -axis crossing

From (b)
$$\rightarrow K = 4$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§5. Refining the Sketch

d. The break-in point

$$(8.32) \rightarrow K = -\frac{\sigma^2 - 4\sigma + 13}{\sigma + 2}$$

$$\rightarrow \frac{dK}{d\sigma} = -\frac{\sigma^2 + 4\sigma - 21}{(\sigma + 2)^2} = -\frac{(\sigma + 7)(\sigma - 3)}{(\sigma + 2)^2}$$

$$\frac{dK}{d\sigma} = 0 \rightarrow \sigma = -7$$

e. The angle of departure from the complex poles

Draw vectors to a point ϵ close to the complex pole $\theta_3 - \theta_2 - \theta_1 = 180^0$

$$\theta_3 - \theta_2 - \theta_1 - 180^\circ$$

 $\rightarrow \tan^{-1}(3/4) - \theta_2 - 90^\circ = 180^\circ$
 $\rightarrow \theta_2 = \tan^{-1}(3/4) - 270^\circ = -233.1^\circ = 126.9^\circ$

 $K = -\frac{1}{G(\sigma)H(\sigma)}$

(8.32)

Nguyen Tan Tien

§6. An Example

Basic Rules for Sketching the Root Locus

1. Number of branches

number of branches = number of closed-loop poles

2. Symmetry

The root locus is symmetrical about the real axis

3. Real-axis segments

The root locus exists to the left of an odd number of real-axis, finite open-loop poles and/or finite open-loop zeros

4. Starting and ending points

The root locus

- begins at the finite and infinite poles of G(s)H(s), and
- ends at the finite and infinite zeros of G(s)H(s)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

7

§6. An Example

5. Behavior at infinity

The root locus \rightarrow straight lines as asymptotes as the locus $\rightarrow \infty$ The asymptotes are given by the real-axis intercept

$$\sigma_a = \frac{\sum_1^n p_i - \sum_1^m z_i}{n-m} \quad \theta_a = \frac{(2k+1)\pi}{n-m} \quad k=0,\pm 1,\pm 2,.$$
 6. Real-axis breakaway and break-in points

$$K = -\frac{1}{G(\sigma)H(\sigma)} \rightarrow \frac{dK}{d\sigma} = 0 \rightarrow \sigma \rightarrow \frac{\sigma_{K_{max}}}{\sigma_{K_{min}}} : \text{breaks away point}$$
 : breaks into point

Using the Routh-Hurwitz criterion

- Forcing a row of zeros in the Routh table will yield the gain
- · Going back one row to the even polynomial equation and solving for the roots

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguven Tan Tien

System Dynamics and Control §6. An Example

Additional Rules for Refining the Sketch

8. Angles of departure and arrival

Assume a point ϵ close to the complex pole or zero. Add all angles drawn from all open-loop poles and zeros to this point

$$\sum_{1}^{n} \theta_{z_i} - \sum_{1}^{m} \theta_{p_i} = (2k+1)180^0$$

Solving for the unknown angle → the angle of departure/arrival

9. Plotting and calibrating the root locus

All points on the root locus satisfy $\angle G(s)H(s) = (2k+1)180^{0}$

The gain, K, at any point on the root locus is given by

$$K = \frac{1}{|G(s)H(s)|} = \frac{1}{M} = \frac{\prod \text{ finite pole lengths}}{\prod \text{ finite zero lengths}}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering


Nguven Tan Tien

System Dynamics and Control

Root Locus Techniques

§6. An Example

- Ex.8.7 Sketching a root locus and finding critical points



Sketch the root locus for the system and find the following

- a. The exact point and gain where the locus crosses the 0.45 damping ratio line
- b. The exact point and gain where the locus crosses the $j\omega$ -axis
- c. The breakaway point on the real axis
- d. The range of K within which the system is stable

System Dynamics and Control

Root Locus Techniques

§6. An Example

Solution



First sketch the root locus

- the real-axis segment $\sigma = -2, -4$
- the root locus starts at the open-loop poles (-2,-4)and ends at the open-loop zeros $(2 \pm j4)$
- a.The exact point and gain where the locus crosses the 0.45 damping ratio line ζ

Searching in polar coordinates, we find that the root locus crosses the $\zeta = 0.45$ line at $3.4 \angle 116.7^{\circ}$ with a gain, K = 0.417


HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

§6. An Example



b. The exact point and gain where the locus crosses the $j\omega$ -axis The closed-loop TF for the system


$$T(s) = \frac{G(s)}{1 + G(s)} = \frac{K(s^2 - 4s + 20)}{(1 + K)s^2 + (6 - 4K)s + (8 + 20K)}$$

The Routh table

A complete row of zeros yields the possibility for imaginary axis roots $s^1:6 - 4K = 0 \rightarrow K = 1.5$

Forming the even polynomial by using the
$$s^2$$
 row with $K = 1.5$
 $s^2:(1+K)s^2+(8+20K)=2.5s^2+38=0 \rightarrow s=\pm j3.9$

The root locus crosses the $j\omega$ -axis at $\pm j3.9$ with a gain of K=1.5HCM City Univ. of Technology, Faculty of Mechanical Engineering



c. The breakaway point on the real axis

From Eq.(8.32)

$$K = -\frac{1}{G(\sigma)H(\sigma)} = -\frac{\sigma^2 + 6\sigma + 8}{\sigma^2 - 4\sigma + 20}$$

$$\Rightarrow \frac{dK}{d\sigma} = \frac{10\sigma^2 - 24\sigma - 152}{(\sigma^2 - 4\sigma + 20)^2} = \frac{(\sigma - 5.279)(\sigma + 2.879)}{(\sigma^2 - 4\sigma + 20)^2}$$

$$\frac{dK}{d\sigma} = 0 \Rightarrow \sigma = -2.879$$

d. From the answer to (b), the system is stable for $0 \le K \le 1.5$

 $K = -\frac{1}{G(\sigma)H(\sigma)}$ (8.32)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Root Locus Techniques

§6. An Example



Run ch8p1 in Appendix B

Learn how to use MATLAB to

- plot and title a root locus
- overlay constant ζ and ω_n curves
- · zoom into and zoom out from a root locus
- · interact with the root locus to find critical points as well as gains at those points
- solve Ex.8.7

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§6.An Example

Skill-Assessment Ex.8.5

Problem Given a unity feedback system that has the forward TF

$$G(s) = \frac{K(s-2)(s-4)}{s^2+6s+25}$$

do the following

- a. Sketch the root locus
- b. Find the imaginary-axis crossing
- c. Find the gain, K, at the $i\omega$ -axis crossing
- d. Find the break-in point
- e.Find the point where the locus crosses $\zeta=0.5$ damping ratio line
- f. Find the gain at the point where the locus crosses the 0.5 damping ratio line
- g. Find the range of gain, K, for which the system is stable

HCM City Univ. of Technology, Faculty of Mechanical Engineering

System Dynamics and Control

Root Locus Techniques

§6. An Example



K(s-2)(s-4) $s^2 + 6s + 25$

- a. Sketch the root locus
- the real-axis segment $\sigma = 2, 4$
- the root locus starts at the open-loop poles $(-3 \pm j4)$ and ends at the open-loop zeros (2,4)
- b. Find the imaginary-axis crossing

$$T(s) = \frac{K(s-2)(s-4)}{(1+K)s^2 + 6(1-K)s + (25+8K)}$$

The Routh table

from row of zero $\rightarrow K = 1$

from s^2 row with $K = 1 \rightarrow 2s^2 + 33 = 0 \rightarrow s = \pm j\sqrt{16.5}$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control §6. An Example

Root Locus Techniques


Solution



c. Find the gain, K, at the $j\omega$ -axis crossing

From the answer to (b), the gain K = 1d.Find the break-in point

From (8.32)



$$\frac{dK}{d\sigma} = 0 \to \sigma = 2.885$$

 $K = -\frac{1}{G(\sigma)H(\sigma)}$

(8.32)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§6. An Example



- e. Find the point where the locus crosses the 0.5 damping ratio line
- Searching along $\zeta = 0.5$ for the 180° point, we find s = -2.42 + j4.18
- f. Find the gain at the point where the locus crosses the 0.5 damping ratio line

For the result in part (e), K = 0.108

g. Find the range of gain, K, for which the system is stable Using the result from part (c) and the root locus, K < 1




HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

§7. Transient Response Design via Gain Adjustment

- The formulas describing percent overshoot, settling time, and peak time were derived only for a system with two closed-loop complex poles and no closed-loop zeros
- Conditions for 2nd-order Approximations
- · Higher-order poles are much farther into the left half of the splane than the dominant 2nd-order pair of poles



- · Closed-loop zeros near closed-loop 2nd-order poles are canceled by proximity of higher-order closed-loop poles
- · Closed-loop zeros not canceled by proximity of higher-order closed-loop poles are far from closed-loop 2nd-order poles

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Root Locus Techniques

§7. Transient Response Design via Gain Adjustment

Design Procedure for Higher Order Systems

- 1. Sketch the root locus for the given system
- 2.Assume 2^{nd} -order system without any zeros, find the gain, K, to meet transient response specification
- 3. Justify the 2nd-order assumption by
- evaluating that all higher-order poles are much farther from the $j\omega$ -axis than the dominant 2nd-order pair (5 times farther)
- verifying that closed-loop zeros are approximately canceled by higher-order poles, or be sure that the zero is far removed from the dominant 2nd-order pole pair to yield approximately the same response obtained without the finite zero
- 4.If the assumptions cannot be justified, the solution will have to be simulated in order to be sure it meets the transient response specification

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control 56 Root Locus Tech

§7. Transient Response Design via Gain Adjustment
- Ex.8.8 Third-order syste



Given the system, design the value of gain, K, to yield 1.52% overshoot. Also estimate the settling time, peak time, and steady-state error

Solution

Use the root locus program to search along the $\zeta=0.8$ damping ratio line for the point where the root locus crosses 1.52% overshoot line. Three points satisfy this criterion: $-0.87 \pm j0.666, K=0.7.36$

-2 -2 -4

 $-1.19 \pm j0.90, K = 12.79$ $-4.60 \pm j3.45, K = 39.64$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nouven Tan Tien

Root Locus Techniques

System Dynamics and Control

57

Root Locus Techniques

§7. Transient Response Design via Gain Adjustment

To test our assumption of a $2^{\text{nd}}\text{-}\text{order}$ system, calculate the location of the 3^{rd} pole

C	ase	closed-loop poles	closed-loop zeros	gain	3 rd closed-loop pole	settling time	peak time	K_v
	1	-0.87 + j0.66	-1.5 + j0	07.36	-9.25	4.60	4.76	1.1
	2	-1.19 + j0.90	-1.5 + j0	12.79	-8.61	3.36	3.49	1.9
	3	-4.6 + j3.45	-1.5 + j0	39.64	-1.80	0.87	0.91	5.9

When the gain is set to meet the transient response, we have also designed the steady-state error. For the example, the steady-state error specification is given by K_{ν} and is calculated

$$K_v = \lim_{s \to 0} sG(s) = \lim_{s \to 0} s \frac{K(s+1.5)}{s(s+1)(s+10)} = \frac{K \times 1.5}{1 \times 10} = 0.15K$$

 $K = \frac{\Pi \text{ pole length:}}{\Pi \text{ pole length:}}$

1)
$$T_s = \frac{4}{\zeta \omega_n}, T_p = \frac{\pi}{\omega_n \sqrt{1-\zeta^2}}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control 58

§7. Transient Response Design via Gain Adjustment

ML

Run ch8p2 in Appendix B

Learn how to use MATLAB to

- enter a value of percent overshoot from the keyboard
- draw the root locus and overlay the percent overshoot line requested
- interact with MATLAB and select the point of intersection of the root locus with the requested percent overshoot line
- interact with the root locus to find critical points as well as gains at those points
- solve Ex.8.8

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

59

Root Locus Techniques

§7. Transient Response Design via Gain Adjustment

GUITool

Explore the SISO Design Tool in Appendix E

The SISO Design Tool is a convenient and intuitive way to obtain, view, and interact with a system's root locus. Section D.7 describes the advantages of using the tool, while Section D.8 describes how to use it. For practice, you may want to apply the SISO Design Tool to some of the problems at the end of this chapter

System Dynamics and Control

60

Root Locus Techniques

§7. Transient Response Design via Gain Adjustment Skill-Assessment Ex.8.6

Problem Given a unity feedback system that has the forward-path TF

$$G(s) = \frac{K}{(s+2)(s+4)(s+6)}$$

do the following

- a. Sketch the root locus
- b.Using a second-order approximation, design the value of $\it K$ to yield 10% overshoot for a unit-step input
- c. Estimate the settling time, peak time, rise time, and steady-state error for the value of *K* designed in (b)
- d.Determine the validity of your 2nd-order approximation

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§7. Transient Response Design via Gain Adjustment

Solution

a. Sketch the root locus

b.Design the value of K to yield 10%OS Searching along the $\zeta = 0.591 (10\%OS)$ line for the 180° point yields -2.028 + j2.768with K = 45.55

c.Estimate
$$T_s, T_p, T_r, e_{step}(\infty)$$

$$T_s = \frac{4}{|Re|} = \frac{4}{2.028} = 1.97s$$

$$T_p = \frac{\pi}{|Im|} = \frac{\pi}{2.768} = 1.13s$$

$$\omega_n T_r \Big|_{\zeta=0.591} \approx 1.8346 \rightarrow T_r = \frac{1.8346}{\sqrt{2.228^2 + 2.768^2}} = 0.000$$

 $\omega_n T_r \approx 1.76\zeta^3 - 0.417\zeta^2 + 1.039\zeta + 1$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§7. Transient Response Design via Gain Adjustment



 $T_r = 0.53s$

System is Type 0
$$K_p = \frac{K}{2 \times 4 \times 6} = \frac{45.55}{48} = 0.949$$

$$K_p = \frac{K}{2 \times 4 \times 6} = \frac{45.55}{48} = 0.949$$

$$\rightarrow e_{step}(\infty) = \frac{1}{1 + K_p} = \frac{1}{1 + 0.949} = 0.51$$

d.Determine the validity of your 2nd-order approximation Searching the real axis to the left of -6 for the point whose gain is $45.55 \rightarrow$ the 3rd pole: $p_3 = -7.94$

The real part of the dominant pole: $p_{1,2} = -2.028$

- $\rightarrow p_3$ is not five times further $p_{1,2}$
- → the 2nd-order approximation is not valid

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nouven Tan Tien

System Dynamics and Control

Root Locus Techniques

§8. Generalized Root Locus

Consider the system requiring a root locus calibrated with p_{1} as a parameter $(s+2)(s+p_1)$

The open-loop TF

pen-loop TF
$$KG(s)H(s) = \frac{10}{(s+2)(s+p_1)}$$

The closed-loop TF

$$T(s) = \frac{KG(s)}{1 + KG(s)H(s)} = \frac{10}{s^2 + 2s + 10 + p_1(s + 2)} = \frac{\frac{10}{s^2 + 2s + 10}}{1 + \frac{p_1(s + 2)}{2s^2 + 2s^2}}$$

Implies that we have the system KG(s)H(s) =

The root locus can now be sketched as a function of p_1 , assuming the open-loop system (8.62)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

Root Locus Techniques

§8. Generalized Root Locus


Skill-Assessment Ex.8.7

Problem Sketch the root locus for variations in the value of p_1 , for a unity feedback system that has the following forward TF

$$G(s) = \frac{100}{s(s+p_1)}$$

Solution Find the closed-loop TF and put it the form

that yields p_1 as the root locus variable



Hence, $KG(s)H(s) = \frac{P1^{s}}{s^2 + 100}$ \rightarrow the root locus

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

§9. Root Locus for Positive-Feedback Systems

- The properties of the root locus change dramatically if the feedback signal is added to the input rather than subtracted

$$R(s)+$$
 $E_{\alpha}(s)$
 $KG(s)$
 $H(s)$

- The closed-loop TF $T(s) = \frac{\pi \sigma(s)}{1 KG(s)H(s)}$ (8.63)
- We now retrace the development of the root locus for the denominator of Eq. (8.63). Obviously, a pole, s, exists when

$$KG(s)H(s) = 1 = 1 \angle k360^{\circ} \quad k = 0, \pm 1, \pm 2, \dots$$
 (8.64)

the root locus for positive-feedback systems consists of all points on the s-plane where the angle of $KG(s)H(s) = k360^{\circ}$

→Refer the textbook

§10. Pole Sensitivity

The root locus exhibits a nonlinear relationship between gain and pole location. Along some sections of the root locus

- · very small changes in gain yield very large changes in pole location and hence performance → high sensitivity to changes
- · very large changes in gain yield very small changes in pole $location \rightarrow low sensitivity to changes in gain$

We prefer systems with low sensitivity to changes in gain

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§10. Pole Sensitivity

- The sensitivity of a closed-loop pole, s, to gain, K

$$S_{S:K} = \frac{K}{s} \times \frac{\delta s}{\delta K} \tag{8.69}$$

s:

the current gain

- Converting the partials to finite increments, the actual change in the closed-loop poles can be approximated

$$\Delta s = s \times S_{s:K} \times \frac{\Delta K}{K} \tag{8.70}$$

: the change in pole location Δs

 $\Delta K/K$: the fractional change in the gain, K

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguven Tan Tien

System Dynamics and Control §10. Pole Sensitivity

- Ex.8.10 Root sensitivity of a closed-loop system to gain variations



Find the root sensitivity of the system at s = -9.47 and -5 + j5. Also calculate the change in the pole location for a 10% change in K

Solution

Differentiating the closed-loop TF denominator, w.r.t. K

$$2s\frac{\partial s}{\partial K} + 10\frac{\partial s}{\partial K} + 1 = 0 \rightarrow \frac{\partial s}{\partial K} = \frac{-1}{2s + 10}$$

$$S_{s:K} = \frac{K}{s} \frac{\delta s}{\delta K} = \frac{K}{s} \frac{-1}{2s+10}$$

HCM City Univ. of Technology. Faculty of Mechanical Engineering

Nguven Tan Tien

System Dynamics and Control

§10. Pole Sensitivity

Sensitivity
$$S_{sK}\Big|_{s=-9.47} = \frac{K}{s} \frac{-1}{2s+10} \Big|_{s=-9.47} \frac{5}{-9.47} \frac{-1}{2 \times (-9.47) + 10} = -0.059$$

The change in the pole location for a 10% change in $\it K$

$$\Delta s = s.S_{s.K} \frac{\Delta K}{K} = (-9.47) \times (-0.059) \times 10\% = 0.056$$

angle in the potential and a 10% change in K
$$\Delta s = s.S_{s.K} \frac{\Delta K}{K} = (-9.47) \times (-0.059) \times 10\% = 0.056$$

$$S_{s.K}\Big|_{s=-5+j5} = \frac{K}{s} \frac{-1}{2s+10} \Big|_{s=-9.47} \frac{50}{-5+j5} \frac{-1}{2 \times (-5+j5) + 10}$$

$$= 1/(1+j1) = (1/\sqrt{2}) \angle -45^{0}$$

The change in the pole location for a 10% change in
$$K$$

$$\Delta s = s.S_{s:K} \frac{\Delta K}{K} = (-5 + j5) \times [1/(1 + j1)] \times 10\% = -j5$$

					11						
K	0	5	10	15	20	25	30	35	40	45	50
							-5 + j2.24				
pole 2	-10	-0.53	-1.13	-1.84	-2.77	-5	-5 - j2.24	-5 - j3.16	-5 - j3.87	-5 - j4.47	-5 - j5

HCM City Univ. of Technology, Faculty of Mechanical Engineering

System Dynamics and Control

§10. Pole Sensitivity

Skill-Assessment Ex.8.9

Problem A negative unity feedback system has the forward TF

$$G(s) = \frac{K(s+1)}{s(s+2)}$$

If K is set to 20, find the changes in closed-loop pole location for a 5% change in K

Solution The closed-loop TF
$$T(s) = \frac{K(s+1)}{s^2 + (K+2)s + K}$$

Differentiating the denominator with respect to
$$K$$

$$2s\frac{\partial s}{\partial K} + (K+2)\frac{\partial s}{\partial K} + s+1 = (2s+K+2)\frac{\partial s}{\partial K} + s+1 = 0$$

$$\rightarrow \frac{\partial s}{\partial K} = -\frac{s+1}{2s+K+2}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§10. Pole Sensitivity

Sensitivity
$$\frac{\partial s}{\partial K} = -\frac{s+1}{2s+K+2} \rightarrow S_{s:K} = \frac{K}{s} \frac{\partial s}{\partial K} = \frac{-K(s+1)}{s(2s+K+2)}$$

$$\rightarrow S_{s:K} \Big|_{K=20} = \frac{-10(s+1)}{s(s+11)}$$

The closed-loop poles when K=20

$$D(s)\Big|_{\kappa=20} = s^2 + 22s + 20 = (s + 21.05)(s + 0.95) = 0$$

$$D(s)\Big|_{K=20} = s^2 + 22s + 20 = (s + 21.05)(s + 0.95) = 0$$
For the pole at -21.05

$$\Delta s = s(S_{sK}) \frac{\Delta K}{K} = -21.05 \frac{-10 \times (-21.05 + 1)}{-21.05 \times (-21.05 + 11)} 0.05 = -0.9975$$

For the pole at
$$-0.95$$

$$\Delta s = s(S_{s:K}) \frac{\Delta K}{K} = -0.95 \frac{-10 \times (-0.95 + 1)}{-0.95 \times (-0.95 + 1)} 0.05 = -0.0025$$

§11. Case Study

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering