Alan and Matt made notes on the first DECADES test flight B751 including the following list of snags that has been compiled. A responsible person has been pencilled in to resolve each of these issues.

	Issue	Person	Complete?
	SSP6 (or any indicator) should be able to be	MG	i i
	greyed out if the user is not bothered about the		
1	status.		
	Check MS1/MS2/MS3 IP addresses on the	MG	
2	aircraft to make sure they are correct.		
	The lower BBR DLU needed resetting before it	MG	
	would accept a flight number. Check that the code		
3	is the same as the other DLUs.		
	Also check the lower BBR TCP routine on the	MG	
4	CRIO.		
	FM Display font is not mono-spaced and is a bit	MG	
5	too small for normal use.		
	FM Laptop Sync button doesn't seem to work. Or	MG	
	if it does then the comparison with a timeserver is		
6	not being done.		
	It would be useful if we could see the DLU time	MG	
	and compare it with timeservers and the tanks. To		
_	make sure all systems are running on the same		
7	time.	DKDM	
	The summary panel of the decades plot is	DKDW	
8	reporting height in ft instead of Kft.	DKDW	
	The summary panel of the decades plot is representing Temp and Dew point to 6 decimal		
9	places. This should probably 2 decimal places.		
3	We should be able to remove the last 2	MG	
	parameters from the PRTAFT packet as they	IVIO	
10	were just used for diagnostics.		
	Connecting to the tanks makes the FM display	MG/DKDW	
	hang until the timeouts have been reached. This		
11	needs to be fixed.		
	Rad-Alt Data not coming in??? - coz it's not	AMW	
12	plugged in		
	Nevz data not possible as cable is plugged into	AMW	
	horace, not decades. And then cable tied in		
13	place!!		
14	GIN Wander angle doesn't plot.	DKDW	
15	Vertical vorticity doesn't plot.	DKDW	
16	Do we need to plot the flight number? No	DKDW	
17	Get abouttime on work laptop.	MG	
	Can we use different colours from horace and	DKDW	
18	decades menu screens?		
	GIN should be ping'ed and shown on main	MG	
19	overview.	140	
00	Flight/Ground should be shown on main overview	MG	
20	(also the other status flags?).	MC	
24	Fish Values/Septic Values are shown in wrong	MG	
21	Tank info indicators.		
22	TAS not calculated properly on horace - around	AMW/DKDW	

	00 / () 1 / ()	T I
	60m/s too low because the deiced temp is	
	connected to DECADES. This needs to be	
	reversed, and the DECADES parameters that	
	currently use Deiced temperature need to use	
	Non-Deiced for the testing period.	
	Time from midnight reporting 37s higher on	AMW
23	DECADES	
	Di/ndi temps good - 1.5C different, probably a cal	AMW
24	issue.	
	JW liquid water cal consts need looking at	AMW
25	DECADES is under-reading by about 20%	
	Lower BBR overreading by around 40% on	AMW
26	DECADES	
	AOSS underreading on DECADES by about half -	AMW
27	connected to the dit issue?	
	Decades vertical wind components are not	DKDW
28	computed	
	Turbulence pressure data is fine for all sensors -	AMW
29	1-2mb differences probably just a cal issue.	
	S9SP not connected properly - need to bell this	AMW
30	through.	
	Plots generally feature erroneous points on	DKDW
	decades where the data trace is instantaneously	
	joined to the plot maximum. This is only on the	
	plot, not the data. Example saved in temp plot	
31	data.pdf also nans appear in the header list.	
	Cabin pressure looks ok, but way too noisy (+/-20	AMW
32	mb!)	
33	Cabin temperature looks real, but needs scaling.	AMW
	Track plot needs changing to GIN params in the	DKDW
	plot window. Currently uses INU params which	
34	don't exist any more.	
	Text plot doesn't work - all params are zero -	DKDW
	probably because some of the ones on the list are	
35	duff, the java seems to crash?	
36	DECADES flight summary doesn't work	DKDW
	Wind data from the quick 5-minute I-pattern were	AMW
	not good. TAS or AOSS may not be being	
	calculated correctly on DECADES? IAS is	
37	compatible with aircraft data from early runs.	
31	compatible with aircraft data from early runs.	