

	A	B	C	D
1	0	—	0	$=C1*\Delta T$
2	z_1	y_1	$=C1+0,5*B2*K_0$	$=C2*\Delta T$
3	z_2	y_2	$=C2+0,5*(B2+B3)$	$=C3*\Delta T$
4	z_3	y_3	$=C3+0,5*(B3+B4)$	$=C4*\Delta T$
5	z_4	y_4	$=C4+0,5*(B4+B5)$	$=C5*\Delta T$
6	z_5	y_5	$=C5+0,5*(B5+B6)$	$=C6*\Delta T$
7	z_6	y_6	$=C6+0,5*(B6+B7)$	$=C7*\Delta T$