

	A	B	C	D	E
1	0	S_0	M_{y0}	0	0
2	1	S_1	M_{y1}	$=D1+0,5*(B1+B2)*\Delta T$	$=E1+0,5*(C1+C2)*\Delta T$
3	2	S_2	M_{y2}	$=D2+0,5*(B2+B3)*\Delta T$	$=E2+0,5*(C2+C3)*\Delta T$
4	3	S_3	M_{y3}	$=D3+0,5*(B3+B4)*\Delta T$	$=E3+0,5*(C3+C4)*\Delta T$
5	4	S_4	M_{y4}	$=D4+0,5*(B4+B5)*\Delta T$	$=E4+0,5*(C4+C5)*\Delta T$
6	5	S_5	M_{y5}	$=D5+0,5*(B5+B6)*\Delta T$	$=E5+0,5*(C5+C6)*\Delta T$
7	6	S_6	M_{y6}	$=D6+0,5*(B6+B7)*\Delta T$	$=E6+0,5*(C6+C7)*\Delta T$
8	7	S_7	M_{y7}	$=D7+0,5*(B7+B8)*\Delta T$	$=E7+0,5*(C7+C8)*\Delta T$

	A	B	C	F	G	H
1	0	S_0	M_{y0}	0	—	—
2	1	S_1	M_{y1}	$=F1+0,5*(A1*B1+A2*B2)*\Delta T*\Delta T$	$=E2/D2$	$=F2/D2$
3	2	S_2	M_{y2}	$=F2+0,5*(A2*B2+A3*B3)*\Delta T*\Delta T$	$=E3/D3$	$=F3/D3$
4	3	S_3	M_{y3}	$=F3+0,5*(A3*B3+A4*B4)*\Delta T*\Delta T$	$=E4/D4$	$=F4/D4$
5	4	S_4	M_{y4}	$=F4+0,5*(A4*B4+A5*B5)*\Delta T*\Delta T$	$=E5/D5$	$=F5/D5$
6	5	S_5	M_{y5}	$=F5+0,5*(A5*B5+A6*B6)*\Delta T*\Delta T$	$=E6/D6$	$=F6/D6$
7	6	S_6	M_{y6}	$=F6+0,5*(A6*B6+A7*B7)*\Delta T*\Delta T$	$=E7/D7$	$=F7/D7$
8	7	S_7	M_{y7}	$=F7+0,5*(A7*B7+A8*B8)*\Delta T*\Delta T$	$=E8/D8$	$=F8/D8$