
1. Charge and logic paths

USB_5V comes from the USB-C port. The existing BQ24074 and USB data path are external to this sheet.



2. Battery discharge switch and USB inhibit




EF_EN comes from the rearm latch below.

Retain the separate motor-enable interlock.


DRIVE_RAW requires a verified regen clamp.

3. Hardware rearm after USB, undervoltage or external fault

Wake the protector, then press SW10 after reset releases. A held button has no new rising edge.



J12 is a fault-injection port. The final hard-short detector is external.



C16-C19 are local bypass capacitors for U11-U14 respectively.

Fixture draft. Verify reset timing, held shorts, charge termination and motor transients before routing.

Nate

Sheet: /
File: rev_f_usb_power_path.kicad_sch

Title: Omni rover | USB and drive isolation

Size: A3	Date:	**Rev: F draft**
KiCad E.D.A. 10.0.8		Id: 1/1