AE333 Mechanics of Materials

Lecture 11 - Torsion
Dr. Nicholas Smith
Wichita State University, Department of Aerospace Engineering

February 24, 2020

schedule

- 24 Feb Torsion
- 26 Feb Bending
- 28 Feb Bending, HW4 Due
- 2 Mar Bending

outline


- torsion
- power transmission
- group problems

torsion

torsion

- Torque is a moment that tends to twist a member about its axis
- For small deformation problems, we assume that the length and radius do not change significantly under torsion
- \bullet The primary deformation we are concerned with in torsion is the angle of twist, denoted with ϕ

shear



The shear strain at points on the cross section increases linearly with ρ , i.e., $\gamma = (\rho/c)\gamma_{\text{max}}$.

torsion formula

- For a linearly elastic material, Hooke's Law in shear will hold ($\tau = G\gamma$)
- This means that, like shear strain, shear stress will vary linearly along the radius

torsion formula

• We can find the total force on an element, *dA* by multiplying the shear stress by the area

$$dF = \tau dA$$

• The torque $(dT = \rho dF)$ produced by this force is then

$$dT =
ho(au dA)$$

torsion formula

• Integrating over the whole cross-section gives

$$T = \int_A
ho(au dA) = rac{ au_{max}}{c} \int_A
ho^2 dA$$

• The integral $\int_A \rho^2 dA$ is also called the Polar Moment of Inertia, J, so we can write

$$au_{max} = rac{Tc}{J}$$

polar moment of inertia


- We know that $J = \int_A \rho^2 dA$, so we can compute this for some common shapes
- For a solid circular cross-section, we have

$$J=\int_0^c
ho^2(2\pi
ho d
ho)=rac{\pi}{2}c^4$$

• For a circular tube we have

$$J=\int_{c_1}^{c_2}
ho^2(2\pi
ho d
ho)=rac{\pi}{2}(c_2^4-c_1^4)$$

example 5.1



The allowable shear stress is 75 MPa. Determine the maximum torque that can be applied to each of the crosssections shown and find the stress acting on a small element at A, B and C.

power transmission

power transmission

- Shafts and tubes are often connected to belts and drives, and the torque, speed, and power are all related
- ullet Power is the rate of work done, for rotation problems, $P=T\omega$
- We are often given the frequency f instead of the angular velocity, ω , in this case $P=2\pi fT$

power units

- In SI Units, power is expressed in Watts 1 W = 1 N m / sec
- In Freedom Units, power is expressed in Horsepower 1 hp = 550 ft lb / sec

shaft design


- We often know the power and frequency of a drive, and need to design a shaft such that the shear stress is acceptable
- ullet We can easily find the torque as $T=P/2\pi f$, we can use this combined with the torsion equation

$$au_{max} = rac{Tc}{J}$$

to find the appropriate shaft diameter.

• For solid shafts we can solve for *c* uniquely, but not for hollow shafts


example 5.4



The steel shaft shown is connected to a 5 hp motor that rotates at $\omega=175$ rpm. If $au_{allow}=14.5$ ksi, determine the required shaft diameter.


group problems

group one



The solid circular shaft is subjected to an internal torque of 5 kN.m. Determine the shear stress at A and B and represent each state of stress on a volume element.


group two



The hollow circular shaft is subjected to an internal torque of 10 kN.m.


Determine the shear stress at A and B and represent each state of stress on a volume element.

group three



The circular shaft is hollow from A to B and solid from B to C. Determine the shear stress at A and B. The outer diameter is 80 mm and the wall thickness is 10 mm.

group four



Determine the maximum shear stress in the 40 mm diameter shaft.