


OFF-PROTOCOL SECONDARY DIAGNOSTIC


Hull polish 5.1909 s > 5.0 s frozen cap

Physical planner (bounded) Own-price response (certified)
Hull mixture mean (not executable)


A Hourly grid energy




B Numerical objective intervals



C Signed gap (unresolved at +5)



D Named-incumbent regret



Gap markers: zero solid, +5 resolution dashed, $-1e-4$ guard dotted.
Synthetic depot-15 finite block; hull mixture mean is not executable.
Signed stored-float intervals; incumbent regret is not an optimal-fleet claim.
Numerical audit only; primary experiment failed its frozen polish budget.