

Site Visit Report

Under the European Union (Drinking Water) Regulations 2014 as amended, the Environmental Protection Agency is the supervisory authority in relation to Irish Water and its role in the provision of public water supplies. This Audit was carried out to assess the performance of Irish Water in providing clean and wholesome water to the visited public supply.

The audit process is a sample on a given date of the facility's operation. Where a finding against a particular issue has been reported this should not be construed to mean that this issue is fully addressed.

Water Supply Zone	
Name of Installation	Banteer
Organisation	Irish Water
Scheme Code	0500PUB1401
County	Cork
Site Visit Reference No.	SV26030

Report Detail	
Issue Date	19/12/2022
Prepared By	David Galvin

Site Visit Detail				
Date Of Inspection	18/10/2022	Announced	No	
Time In	11:40	Time Out	12:35	
EPA Inspector(s)	David Galvin		'	
Additional Visitors				
Company Personnel	Irish Water: Tommy Roche, Ciaran Connelly			
Cork County Council, Jason O'Donoghue				



Summary of Key Findings

(1) Disinfection consists of Chlorination and UV. The audit found that the disinfection system was operating satisfactorily during the inspection



Introduction

The Banteer Public Water Supply (PWS) produces approximately 759m3/d of water serving a population 1,412 (EDEN figures). The audit focused on the disinfection system at the Banteer PWS. The site has been assessed under Irish Water's Disinfection Programme and reported to the EPA as having been fully commissioned and available on telemetry on 18/12/2020.



Supply Zones Areas Inspected

The audit assessed the chlorination and UV disinfection system at the Banteer WTP

>

1. Disinfection Programme Audits 2022

	Answer
Is chlorination used for primary disinfection?	No
Comment	
UV is the primary disinfection/chlorination is secondary	
	Answer
Did Irish Water confirm the type of chlorine disinfectant in use?	Yes
	Answer
Are there duty and standby chlorine dosing pumps in place?	Yes
	Answer
In there automatic quitabover in the avent of failure of one of the oblering decina	
Is there automatic switchover in the event of failure of one of the chlorine dosing pumps?	Yes
	Answer
Is the chlorine dosing rate flow proportional?	Yes
	Answer
Is the chlorine dosing rate fixed?	Not Applicable
	Answer
Can IW / LA confirm the target residual chlorine level for the final water leaving the plant?	Yes
	Answer
Is there a continuous residual chlorine monitor on the final water?	Yes
· ·	
	Answer

	Answer
Are there low and high chlorine alarm settings?	Yes
	Answer
Is there an alarm response procedure available on site for responding to chlorine alarms?	Yes
	Answer
Is there automatic shutdown of the supply in the event of the chlorine level dropping below the low chlorine alarm setting or rising above the high chlorine alarm setting?	Yes
	Answer
Are service due / monitoring instrument calibration dates for the chlorine monitors	Yes
within date?	
Comment	
	Answer
	Answer Yes
Comment	Yes
Comment	
Comment	Yes
Comment Is the site specific contact time being achieved?	Yes
Is the site specific contact time being achieved? Is the minimum effective contact time of 15 mg. min/l being achieved? Is the residual chlorine level ≥ 0.1 mg/l at the extremity of the distribution	Yes Answer Yes
Is the site specific contact time being achieved? Is the minimum effective contact time of 15 mg. min/l being achieved?	Answer Yes Answer
Is the site specific contact time being achieved? Is the minimum effective contact time of 15 mg. min/l being achieved? Is the residual chlorine level ≥ 0.1 mg/l at the extremity of the distribution	Answer Yes Answer
Is the site specific contact time being achieved? Is the minimum effective contact time of 15 mg. min/l being achieved? Is the residual chlorine level ≥ 0.1 mg/l at the extremity of the distribution	Answer Yes Answer Yes
Is the site specific contact time being achieved? Is the minimum effective contact time of 15 mg. min/l being achieved? Is the residual chlorine level ≥ 0.1 mg/l at the extremity of the distribution network?	Answer Answer Yes Answer Answer

Are there duty and standby UV units in operation?	Yes
	Answer
Is there automatic switchover between the duty and standby UV units in the event of failure of the duty unit?	Yes
	Answer
Is there automatic plant shutdown in the event of UV units failing or operating outside of their validated range?	Yes
	Answer
Is there continuous monitoring of the UV units to verify operation within validation range at all times?	Yes
	Answer
Can data trends from the online UV monitor(s) be viewed on-site?	Yes
	Answer
Is there an alarm response procedure available on site for responding to UV alarms?	Yes
	Answer
Are service due / monitoring instrument calibration dates for the UV units within date?	Yes
	Answer
Is a copy of the validation certificate for the UV disinfection system available on site ?	Yes
	Answer

		Answer
1.27	Have all relevant staff received training on the disinfection upgrades?	Yes

Recommendations

Subject	Banteer-Disinfection Audit	Due Date	19/01/2023		
Action Text	Recommendation				
	Irish Water is responsible for ensuring a safe and secure supply of drinking water. To address these issues, Irish Water should implement the following recommendations without delay.				
	Irish Water should ensure that the disinfection stage continues to be suitably managed and operated at all times.				
	Follow-Up Actions required by Irish Water				
	During the audit, Irish Water representatives were advised of the audit findings and that action must be taken as a priority by Irish Water to address the issues raised. This report has been reviewed and approved by Criona Doyle, Drinking Water Team. Irish Water should submit a report to the Agency on or before 19/01/2023 detailing how it has dealt with the issues of concern identified during this audit.				
	The report should include details on the action taken and planned to address the various recommendations, including time frame for commencement and completion of any planned we				
	The EPA also advises that the findings and recommendations from this audit report should, where relevant, be addressed at all other treatment plants operated and managed by Irish Wa				
	Please quote the Compliance Plan Number DW20220153 in any future correspondence in relation to this Report.				