
Coupling-server scheduling stages — coupling_history
orchestrator stage [s]
10^{2}
10^{1}
10^{0}
10^{-1}
10^{-2}
10^{-3}
0.00
0.25
0.50
0.75
1.00
1.25
1.50
1.75
coupling time [s]
wait: solid geometry
send: geometry
wait: fluid force
server force processing
send: force
wait: solid diagnostic