## Required Buoy Deck Crane Encoder for USCGC Cypress

- 1. Background. CGC CYPRESS's buoy deck Crane Encoder has failed.
- 2. **Scope**. Vendor shall provide replacement MULTI-TURN ethernet Encoder (P/N YMD-15180) as well as Angled M12 Socket Cable 10M (P/N YMD-12698). A program change is required when replacing obsolete Encoder (YMD-12674).
- 3. **Objective.** The objective of this requirement is to replace obsolete encoder and conduct program change with crane as well as calibrating settings.
- 4. **Tasks**. The contractor shall provide one of each: PN: YMD-15190 Multi-turn ethernet encoder nanocoated. P/N: Angled M12 Socket Cable 10M.
- 5. **Delivery**. Contractor shall provide once available.
- 6. Government furnished property. N/A
- 7. Security Requirement. N/A
- 8. Place of performance: CGC CYPRESS (WLB – 210) 15250 190651 CHINIAK HWY

KODIAK AK, 99615

- 9. Period of performance- at earliest convenience
- 10. Points of Contact.

10.1. USCG-SFLC-IBCTPL Asset Management: EMCS Daniell Hurtado. Daniell.e.hurtado@uscg.mil 10.2. USCGC CYPRESS: CWO2 Edward A. Cordova, email: <a href="mailto:edward.a.cordova@uscg.mil">edward.a.cordova@uscg.mil</a> Phone: 530-933-8984