

Statement of Work for LabRAM II H and RAM-5 Service

1.0 Introduction

The Naval Surface Warfare Center Indian Head Division (NSWC IHD) requires maintenance and repair services on Resodyn LabRAM IIH and RAM-5 mixers. The LabRAM IIH and RAM-5 mixers are currently used for energetic mixing, as a quicker and safer alternative to conventional mixing. The LabRAM IIH has had some issues with vacuum function and after attempting to fix, there was no power to the mixer and could not be fixed by NSWC IHD personnel. The contractor will determine what is wrong with the LabRAM IIH. After fixing the issue, preventative maintenance will be performed on the mixer. Additionally, the RAM-5 mixer has not been serviced since 2019 and Resodyn personnel will perform a diagnostic check and perform necessary preventative maintenance. NSWC Indian Head will provide an electrician to assist Resodyn Acoustic Mixers Incorporated.

2.0 Scope

The Contractor shall identify and perform required maintenance and repair services on two identified Resodyn mixers.

Equipment: LabRAM IIH (P/N H100000140) and RAM-5 (RAM 5020 P/N 902600)

Purpose:

1. To perform diagnostic work on the LabRAM IIH.
2. To resolve all LabRAM IIH power and vacuum issues.
3. To perform preventative maintenance on the LabRAM IIH and RAM-5 mixers.
4. Provide recommendations for any additional maintenance needed.

End Expectations:

1. Restore LabRAM IIH functionality with power and ability to run mixer.
2. Restore LabRAM IIH vacuum function.
3. Resodyn to train engineers and operators on vacuum best practices and troubleshooting.
4. Ensure LabRAM IIH and RAM-5 preventative maintenance completed, and mixer status is up to date.
5. Resodyn to provide a list of any further maintenance recommendations after inspection of LabRAM IIH and RAM-5 mixers.

3.0 Requirement

The Contractor shall perform the following services for each of the mixers listed below:

LabRAM II H (P/N H100000140)

- Install replacement power supply
- Install replacement Accelerometer
- Install replacement Bellows
- Operational check of Purge System
- Operational check of Chiller System
- Operational check of HMI
- Operational check of Vacuum System
- Operational check of Resonator and Springs
- Operational check of Vessels and Vessel Holder
- Calibration of Accelerometer

RAM-5 (RAM 5020 P/N 902600)

- Change Oil, Filter, and Breather
- Install replacement Accelerometer
- Install replacement Z Accelerometer
- Install replacement Hydraulic Hoses
- Install replacement JV Parts
- Install replacement bellows
- Operational check and Inspection of the Purge System
- Operational check and Inspection of the Chiller System
- Operational check and Inspection of the Electrical System
- Operational check and Inspection of the Vacuum System
- Operational check and Inspection of the Vessels
- Calibration of Accelerometer

4.0 Security Requirements

The Contractor shall coordinate base access in advance of scheduled Maintenance with the Technical Point of Contact.

5.0 Place of Performance

Naval Surface Warfare Center, Indian Head Division

M Department

BLDG 1119

Indian Head, MD 20640

M Department

BLDG 905

Indian Head, MD 20640

6.0 Period of Performance

The Period of Performance shall be three months from the date of award.

7.0 Technical Point of Contact

Alexis Burnette

Phone Number: (301) 744-4912

Email: alexis.r.burnette.civ@us.navy.mil