

FA8604-25-R-B022

Materials Handling System at Laughlin AFB, Texas 47 Flight Training Wing (FTW) MXD,
Buildings 65 and 68

Question Set #3

28 May 2025

1. Q. What are the dimensions of the framed openings for the conveyor and how far off the ground should the bottom of the opening be?
A. Per Appendix D, 3.2.9 The modified panels shall be completely framed with aluminum to provide a clear opening of a minimum of 51 plus or minus 1 inches high from top to bottom. The gap between the bottom of the panel opening and the frame of the conveyor shall not be greater than 1/2-inch. There shall be a gap of 5 plus or minus 1 inches on both sides of the panel opening and conveyor frame to allow packages that are wider than the conveyor to pass through. All openings shall permit unobstructed passage of property moving along the conveyor path.
2. Q. Should there still be windows in the panels with the conveyor openings?
A. The conveyor opening will take the place of the window.
3. Q. Should there still be windows in the panels with the HVAC units?
A. A window may be omitted where an HVAC unit is installed.