



02/28/2024

Dear Tenant Agency Representative:

Pursuant to the Code of Federal Regulations all building owners are required to provide notification of the presence, location, and quantity of asbestos containing materials (ACM) and presumed asbestos containing materials (PACM) in their facilities. This notification is provided as a safeguard, to ensure tenant agencies occupying the facility are aware of this information.

Asbestos containing material is present in the John Weld Peck Building (OH0189CN) in the following forms, locations, and quantities:

Type	Location	Quantity
Fittings on Fiberglass Line	Throughout Building	21200 ea
Tank Insulation	Sub-Basement Mechanical Room	800 sf
Duct Insulation	Throughout	19000 sf
Elevator Door Insulation	Throughout	1300 sf
Mastic on AHU Supply Duct	Throughout Building Supply Duct	13600 sf
Caulk (Painted Grey)	Sub-Basement Mechanical Room	10 lf
Electrical Conduit Putty	3rd Floor West Hall Telephone Closet	100 sf
Interior Window Glazing	Throughout Building	Undefined ¹
Mastic on Car Shell	Freight Elevator Car Shell	500 sf
Insulation on Converter Tank	Penthouse	500 sf
Floor Tile and Mastic	Throughout Building	634350 sf
Ceiling Tile	1st & 3rd Floor	5400 sf
Gold HVAC Sealant	7th Floor Hallway	Undefined ²
Mastic Associated with 12"x12" White Floor Tile with Tan Specks	2nd, 7th, and 9th Floor	Undefined ²
Mirror Mastic	Throughout	Undefined ²
Fire Doors	Throughout	Undefined ²

Should GSA construction or maintenance activities in areas accessible to tenants or the public disturb or necessitate removal of ACM or PACM, we will notify you prior to the start of any such work. All relevant OSHA and EPA regulations governing ACM and PACM maintenance, removal, and disposal are strictly adhered to, and only licensed and certified asbestos removal contractors are employed for this work.

Notification of the presence, location, and quantity of ACM and PACM in the facility must be provided to all contractors performing work in the facility. Tenant agencies performing construction in their space must notify GSA Property Management prior to the start of any work, so information is shared accordingly.

Please be assured the condition of all ACM and PACM within the facility is monitored. To ensure transparency, asbestos inspection reports for this facility are available for your review. If you have any questions, please contact our Property Management staff at 513/246-4472.
