

1.0 Introduction

This Statement of Work (SOW) defines the requirements for acquiring services to support the mission of the Naval Air Warfare Center, Weapons Division (NAWCWD), Command Communications Department Artifacts Program. The contractor shall provide all personnel, equipment, tools, materials, supervision, and other items necessary to perform the tasks described herein.

2.0 Scope

The scope of this effort includes repainting the Douglas AD-4N Skyraider display aircraft located in front of McLean Laboratory, building 00010, onboard NAWCWD in China Lake, California.

3.0 Applicable Documents

The contractor must follow the requirements and paint scheme outlined in the Skyraider Paint Scheme document. This document will be incorporated by reference.

4.0 Requirements/Tasks

- 4.1 Prepare and protect the area around the aircraft.** This task includes laying and securing tarps around the aircraft to protect the concrete pad under the aircraft and the surrounding areas.
- 4.2 Prepare the aircraft for painting.** This task includes applying painter's tape as appropriate to areas that will not be painted, removing old paint, and sanding surfaces as necessary.
- 4.3 Paint the aircraft.** This task includes painting the aircraft in accordance with the Skyraider Paint Scheme document, using durable, UV-resistant polyurethane paints over an epoxy primer designed to withstand extreme temperatures. **Safety Data Sheets for all paint used must be provided to Government POCs listed in 12.0.**
- 4.4 Apply finishing touches.** This task includes correcting any mistakes, applying a high quality gloss or semi-gloss finish, removing any overspray, and ensuring that all insignias are placed and painted in accordance with the Skyraider Paint Scheme document.
- 4.5 Remove all materials, equipment, and dispose of all refuse associated with the tasks.** This task includes cleaning up the work site, disposing of any accumulated trash and used materials, and disposing of any hazardous waste in accordance with OSHA regulations.

5.0 Deliverables

Deliverable	Description	Due Date	Acceptance Criteria
Painting completed	Skyraider display aircraft	See the purchase order	Skyraider is painted in accordance with Skyraider paint scheme document with no deviations.

6.0 Period of Performance

Determined upon award of contract.

7.0 Place of performance

All work will be performed at the government site, onboard Naval Air Weapons Station (NAWS) China Lake, California. The specific work site is Michelson Laboratory, building 00010.

8.0 Government-Furnished Property (GFP)/Information (GFI)

No Government-furnished property or information will be provided.

9.0 Security Requirements

Base access is required for this effort. The contractor will provide all required documents for base access to the Command Communications Department Office Manager upon request and comply with all NAWS China Lake installation access policies.

No security clearance is required for this effort.

10.0 Quality Assurance/Performance Standards

The government POCs will evaluate the finished product (i.e., the fully repainted aircraft) with the specifications in accordance with the paint scheme provided. The contractor shall observe all appropriate safety standards in accordance with all OSHA standards and the U.S. Army Corps of Engineers (USACE) Safety and Health Requirements Manual (EM 385-1-1). Fall protection is also required for all work that is 4 feet or more off the ground.

11.0 Invoicing and Payment

Defined by the purchase order.

12.0 Points of Contact

Government POCs:

TBD