

Controlled Unclassified Information (CUI) Only

Bid Inquiry Contractor Report All Inquiries

Project: FY25 WAD ELECTRICAL SATOC **Review:** Bidder Inquiry (00001)

(sorted by CommentID)

Displaying 40 inquiries.

Id	Discipline	Sheet	Detail	Spec
11395924	Specifications	Block 10 of 1442	1442	1442
Comment Classification: UNCLASSIFIED (U)				
Block 10 of form 1442 states: "Competition will be limited to 8(a) certified firms who have offices within SBA's Region III which includes Delaware, Pennsylvania, Washington D.C., Virginia, and West Virginia." 1. Maryland is included in SBA's Region III. Did the Government unintentionally omit Maryland? 2. If the Government intentionally omitted Maryland, please be aware that SBA does not have the legal ability to exclude a state from eligibility for 8(a) contracts. SBA can only limit geographic eligibility by excluding a District Office of the SBA. 3. Please clarify that competition will include 8(a) companies that have offices within SBA's Region III, including the Baltimore District Office.				
On: Jun 17 2025.				
	Government Response. . Block 10 of the SF 1442 will be clarified to include Maryland. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11397827	Contracting			00 21 16
Comment Classification: UNCLASSIFIED (U)				
Will the Sample Project be awarded as a Task Order?				
On: Jun 18 2025.				
	Government Response. . The sample project may become a task order, but that is up to the discretion of the Government. The purpose of this sample project is for bidders to showcase their abilities, and for the Government to determine which bidder can provide it with the best value. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11399348	Building Design & Engineering	52		26
Comment Classification: UNCLASSIFIED (U)				
Are As-Built drawings available for any work that may have altered the Administration Building's electrical system?				
On: Jun 19 2025.				
	Government Response. . As-Built drawings will be provided in the upcoming amendment. Please see the provided drawings. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11399351	General	52		26
Comment Classification: UNCLASSIFIED (U)				
What level of coordination will be available with facilities? We need facilities support for taking equipment out of service, manipulating switches, LOTO, etc.				
On: Jun 19 2025.				
	Government Response. . WA Staff will assist with de-energization by opening breakers upstream and downstream of the equipment (LOTO). The contractor will also be responsible for applying their own LOTO. When coordination with PEPCO, the local power utility, is needed, then it will be the contractor's responsibility. WA will need to be included within the communication with PEPCO. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11399353	General	52		01
Comment Classification: UNCLASSIFIED (U)				
Will advanced notice be given about any plant activities that may affect our work and/or schedule?				

On: Jun 19 2025.

Government Response. . Washington Aqueduct will provide any plant activities that might affect the contractor's work during the progress meeting. Contractors shall submit any planned outages as part of their preliminary schedule as well as 30 days in advance of planned work, and the work can commence after the Government has agreed with the proposed dates. The Government will strive to provide contractors a week in advance notice if planned outages suddenly need to be halted and rescheduled. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399354	Electrical	52		26
-----------------	------------	----	--	----

Comment Classification: **UNCLASSIFIED (U)**

Is there a Line Diagram available of the Administration Building's electrical system?

On: Jun 19 2025.

Government Response. . Line Diagram will be provided in the upcoming amendment. Please see the provided drawings. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399638	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

1. Will you supply Schematics and As-Built Drawings for Existing Distribution and Control / Annunciation and Existing P87 & P88 Distribution Drawings?

On: Jun 20 2025.

Government Response. . Please see the provided drawings for P87 and P88 in the upcoming amendment. As for the annunciator, the control diagrams are not readily available to the Government. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399640	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

2. When was the last successful Transfer operation without issues?

On: Jun 20 2025.

Government Response. . Transferring between the feeder and generator has been conducted successfully several times over the past year. As for transferring between the incoming feeders, the last successfully attempt was back in 2022. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399641	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

2. When was the last successful Transfer operation without issues?

On: Jun 20 2025.

Government Response. . Please refer to the answer for RFI ID# 11399640. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399643	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

3. When the Generator was installed can the commissioning report be supplied?

On: Jun 20 2025.

Government Response. . The report is not readily available to the Government. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399644	Electrical	52		002116
Comment Classification: UNCLASSIFIED (U)				
3. When the Generator was installed can the commissioning report be supplied?				
On: Jun 20 2025.				
	Government Response. . Please refer to the answer for RFI ID# 11399643. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11399645	Electrical	52		002116
Comment Classification: UNCLASSIFIED (U)				
4. When the Transfer Switch was installed can the commissioning report be supplied?				
On: Jun 20 2025.				
	Government Response. . The report is not readily available to the Government. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11399648	Electrical	52		002116
Comment Classification: UNCLASSIFIED (U)				
4. When the Transfer Switch was installed can the commissioning report be supplied?				
On: Jun 20 2025.				
	Government Response. . Please refer to the answer for RFI ID# 11399645. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11399650	Electrical	52		002116
Comment Classification: UNCLASSIFIED (U)				
5. Can the issue be replicated reliably or is it intermittent?				
On: Jun 20 2025.				
	Government Response. . The issue with the Generator occurred every time the equipment was run. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11399651	Electrical	52		002116
Comment Classification: UNCLASSIFIED (U)				
5. Can the issue be replicated reliably or is it intermittent?				
On: Jun 20 2025.				
	Government Response. . Please refer to the answer for RFI ID# 11399650. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11399652	Electrical	52		002116
Comment Classification: UNCLASSIFIED (U)				
6. Has the Grounding Electrode Conductor been tested and can report be supplied?				
On: Jun 20 2025.				
	Government Response. . The grounding conductor has not been tested yet, and the Government does not have any corresponding report. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11399655	Electrical	52		002116
Comment Classification: UNCLASSIFIED (U)				

6. Has the Grounding Electrode Conductor been tested and can report be supplied?

On: Jun 20 2025.

Government Response. . Please refer to the answer for RFI ID# 11399652. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399658	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

7. Is the existing P87 & P88 Feeder Secondary Transformer to be PM'ed as well?

On: Jun 20 2025.

Government Response. . The current scope only mentioned preventative maintenance to be done on P87 & P88. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399661	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

7. Is the existing P87 & P88 Feeder Secondary Transformer to be PM'ed as well?

On: Jun 20 2025.

Government Response. . Please refer to the answer for RFI ID# 11399658. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399663	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

8. Does the Fire Alarm Annunciator indicate issue as well?

On: Jun 20 2025.

Government Response. . The Annunciator is for the emergency generator. An alarm would go off whenever the generator experienced any issues listed on the panel. The maintenance staffs have confirmed that whenever the generator changed from Auto to Hand, the alarm would go off. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399665	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

9. Is Generator a Life Safety or Emergency Back up?

On: Jun 20 2025.

Government Response. . The Generator is an emergency backup incase both feeder P87 & P88 goes down. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399666	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

9. Is Generator a Life Safety or Emergency Back up?

On: Jun 20 2025.

Government Response. . Please refer to the answer for RFI ID# 11399665. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399668	Electrical	52		002116
-----------------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

10. Can you supply the O&M with the Transfer Switch and the Generator?

On: Jun 20 2025.

Government Response. . No. The Government does not have the Operation and Maintenance manual on hand, but it should be readily available on the internet. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399669	Electrical	52		002116
----------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

11. What is the sequence of events before the failure event occurs?

On: Jun 20 2025.

Government Response. . The failure occurred after the generator was placed in Hand Mode for testing. Washington Aqueduct staff struggle with returning the generator back into Auto mode. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399672	Electrical	52		002116
----------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

12. Has the phasing been verified to match all sources?

On: Jun 20 2025.

Government Response. . The phasing has been confirmed to be in matching. The maintenance staffs performed a quarterly transfer from the feeder to the generator. No issues with the phasing have ever occurred. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399674	Electrical	52		002116
----------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

13. Are the PM's to include IR Scanning?

On: Jun 20 2025.

Government Response. . The Performance Work Statement did not mention IR Scanning, so it is not necessary. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399676	Electrical	52		002116
----------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

14. Can you supply the Power Quality and Harmonics Reports for this System?

On: Jun 20 2025.

Government Response. . The report is not readily available to the Government. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399679	Electrical	52		002116
----------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

14. Can you supply the Power Quality and Harmonics Reports for this System?

On: Jun 20 2025.

Government Response. . Please refer to the answer for RFI ID# 11399676. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399681	Electrical	52		002116
----------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

15. Has the Generator Control Board been replaced and what were the results?

On: Jun 20 2025.

Government Response. . Minor repairs were performed in the past. Attempts at full replacement were unsuccessful due to struggle with locating parts. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399684	Electrical	52		002116
----------	------------	----	--	--------

Comment Classification: **UNCLASSIFIED (U)**

16. Has the Transfer Switch Control Board been replaced and what were the results?

On: Jun 20 2025.

Government Response. . The control board for the transfer switch have not been replaced yet. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399829	Construction Management			Sec 1.3.3.2.2
----------	-------------------------	--	--	---------------

Comment Classification: **UNCLASSIFIED (U)**

Requires that on proposals we submit, each item "exceeding \$2,500 must be supported by a minimum of three quotations from suppliers/installers". We request that this requirement be eliminated and that pricing justification be provided on an "as needed" basis. We have established relationships with our best priced and most responsive suppliers and vendors. And this process will be antagonizing to suppliers who are repeatedly asked for quotes that are not then executed. Furthermore, this additional requirement will slow down the proposal process that require a timely turnaround.

On: Jun 20 2025.

Government Response. . No, this requirement will not be removed. This provision will be addressed to the awardee on a task order level during ordering procedures. This is not required for the solicitation sample project. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399830	Construction Management			Sec 1.3.6
----------	-------------------------	--	--	-----------

Comment Classification: **UNCLASSIFIED (U)**

Detailed Estimate requires contractor to "solicit, as a minimum, three bids/quotes on non-Means priced work that is to be subcontracted." Request that this requirement be eliminated. We have established relationships with specialty contractors that have a history of technical competency and competitive pricing. We would like to preserve this ongoing relationship by using these reliable subcontractors without getting lowest pricing.

On: Jun 20 2025.

Government Response. . No, this requirement will not be removed. This provision will be addressed to the awardee on a task order level during ordering procedures. This is not required for the solicitation sample project. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399831	Construction Management			Sec 1.24
----------	-------------------------	--	--	----------

Comment Classification: **UNCLASSIFIED (U)**

This section mentions the use of Resident Management System (RMS) and QCS for uploading and monitoring information with the government. Are these programs still being used, including for this contract?

On: Jun 20 2025.

Government Response. . As this is a sample project, bidders only need to submit a proposal. However, typically when task orders are issued, the Government will utilize RMS to manage the project. On: Jul 02 2025

Government Response. . As this is a sample project, bidders only need to submit a proposal. However, typically when task orders are issued, the Government will utilize RMS to manage the project. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399832	Construction Management			Sec 1.24.8
----------	-------------------------	--	--	------------

Comment Classification: **UNCLASSIFIED (U)**

This section directs the contractor to use compact disks as the government's preferred method for submittals of updates, payment requests, and other data. Please confirm or update the government's preferred method of transferring information from the contractor.

On: Jun 20 2025.

Government Response. . This section mentioned that the Government preferred method of submission is through email, and compact disk will only be submitted when this is not possible. For clarity, the Government will make some edits to this section. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399833	Construction Management			Sec 1.29
-----------------	-------------------------	--	--	----------

Comment Classification: **UNCLASSIFIED (U)**

This section says that the contractor will be required to provide temporary facilities at no expense to the government. This cost (when temporary toilets are required) is customarily included as a direct cost in project proposals. Please confirm that this cost will be allowed in our proposal.

On: Jun 20 2025.

Government Response. . The Government intends to edit this provision, and the revised document will be reposted. Toilets will be available for contractors depending on the location of the work that will be mentioned within the task order scope. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11399840	Construction Management			spec
-----------------	-------------------------	--	--	------

Comment Classification: **UNCLASSIFIED (U)**

Has the Transfer Switch Control Board been replaced and what were the results?

On: Jun 20 2025.

Government Response. . Please refer to the answer for RFI ID# 11399684. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11400141	Contracting	45	Bonding	Bonding requirements
-----------------	-------------	----	---------	----------------------

Comment Classification: **UNCLASSIFIED (U)**

Will you require a bid bond for the seed project and a bond ability letter for the \$8m, or would you just require a bond ability letter?

On: Jun 20 2025.

Government Response. . No, a bid bond is not required for this sample project. The awardee will be expected to provide bonds assurance after award notification. On: Jul 02 2025

Current Request Status: **Request Closed**

Information for this report is procurement sensitive.

11400155	Construction Phasing	52	generator	generator
-----------------	----------------------	----	-----------	-----------

Comment Classification: **UNCLASSIFIED (U)**

1. From the site visit it was discovered that we need to confirm if there are any test reports
2. Can we confirm that the generator is operational.
3. Is testing allowed before submitting bid.
4. Can work be performed during normal working hours.
5. Can we have a copy of the sign-in.
6. Can you please confirm if there is an existing issue with the generator fuel heater; we need to confirm if it is heating the fuel oil
7. Can we schedule a second visit
8. Would you consider making task order Time and Materials due to the unknown, we would propose doing a diagnosis before providing a permanent repair price.

On: Jun 20 2025.

Government Response. . 1.The Government does not have any readily available reports.
2.Generator is operational.
3.No testing will not be allowed before submitting bid.
4.Yes, it is possible to work during normal hours as long as the incoming feeders are isolated while the generator is

	running, and vice versa. 5.Attendance sheet will be posted along with the amendment. It will be posted on SAM and PIE 6.WA staff has confirmed that the heater is currently inoperable. 7.No second visit will be allowed. 8.No, task order will be firm-fixed price. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11400259	Construction Phasing	52	generator	generator
Comment Classification: UNCLASSIFIED (U) During the walk through it was mentioned that the fuel heater was not working. The generator is operating, but sometimes it will flip from automatic to hand position on its own. Having issues with one of the transfer switches. Both need to be checked, repairs made and maintenance. We would like to confirm existing issues they are experiencing. On: Jun 20 2025.				
	Government Response. . Bidders are allowed to include a list of assumptions within their proposal. However, at this point in time, the Government is not considering a second site visit. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				
11403911	Electrical	01	01	01
Comment Classification: UNCLASSIFIED (U) 1) Can you provide pictures of damaged connector on MV feeder? 2) Do you have original control wiring drawings for generator/ats annunciator? 3) Can you provide sequencing of electrical interlock of mv feeders in switchboard? Is there a auto feature for switching? 4) What is the distance for MV feeder connection from switchboard to origination point/manhole? 5) Do you have a POC you currently work with for generator services? On: Jun 24 2025.				
	Government Response. . 1.Please see the attached photos provided in the upcoming amendment. 2.The report is not readily available to the Government. 3.Swapping from one feeder to the other must be done manually. The two feeders are kirk-key interlocked. 4.The incoming power to the Admin Building comes from Dalecarlia Pumping Station, with around 4 manholes in between. The conductors coming to the Admin Building should be around 700-800 ft. 5.The Government currently do not have a POC for the generator services. On: Jul 02 2025			
	Current Request Status: Request Closed			
Information for this report is procurement sensitive.				

Report Complete

Controlled Unclassified Information (CUI) Only
 Patent 11/892,984 ProjNet property of ERDC since 2004.