

U.S. COAST GUARD JUSTIFICATION FOR OTHER THAN FULL AND OPEN COMPETITION**SIMPLIFIED ACQUISITION PROCEDURES (SAP) FOR FAR 12.102 (a)****PURCHASE REQUEST OR REQUISITION NUMBER:****ESTIMATED TOTAL VALUE, INCLUDING OPTIONS:**
(Over Micro-Purchase Threshold, but up to the SAT)**AUTHORITY****JUSTIFICATION TYPE**

☒	FAR 12.102 (a)	ONLY ONE SOURCE REASONABLY AVAILABLE (e.g., urgency, exclusive licensing agreements, or industrial mobilization).
☐	FAR 5.201(c)(3), FAR 11.204, FAR 12.102 (a)	BRAND NAME – Items peculiar to one manufacturer: The particular brand name, product, or feature is essential to the Government's requirements, and market research indicates other companies' similar products, or products lacking the particular feature, do not meet, or cannot be modified to meet, the agency's needs.

BRIEF DESCRIPTION OF SUPPLIES OR SERVICES REQUIRED AND THE INTENDED USE:

The Aviation Logistics Center (ALC) and Medium Range Recovery (MRR) Product Line intends to repair the following item on a sole source basis. This requirement is for items used on the MH-60T aircraft. These items are required for replacement during routine maintenance because of failures, corrosion and/or damage

Quantity	Description	National Stock Number	Part Number
8	EGI 764+429+JAIC	1680-01-HS1-9691	HG9869K1-001

SUGGESTED SOURCE NAME, ADDRESS, & UNIQUE ENTITY IDENTIFIER (UEI):

The item to be repaired under this acquisition is a specialized item that has been designed and manufactured by:
HONEYWELL INTERNATIONAL INC.
 21111 N 19th Avenue
 Phoenix, AZ 85027-2708
 UEI: JCCHJ122AVW9

RATIONALE FOR JUSTIFICATION TYPE SELECTED ABOVE TO INCLUDE RELEVANT INFORMATION GAINED THROUGH YOUR MARKET RESEARCH TO SUPPORT THE JUSTIFICATION TYPE:

As the Original Equipment Manufacturer (OEM) of this item, Honeywell International Inc (Cage Code 0BFA5) owns all rights to the technical data, specifications, and drawings required for its repair. The item to be repaired is complex and must meet critical operational and reliability requirements, the achievement of which require unique production techniques and extensive and/or sophisticated testing. The Government does not own or possess any rights to the technical data, specifications, and drawings required to repair this item and it has been determined that it is uneconomical to purchase them. The OEM is the only approved source with the ability to support the evaluation, testing and repair of this item. Therefore, the USCG is conducting a sole source acquisition.

CONTRACTING OFFICER - FAIR AND REASONABLE PRICE DETERMINATION METHODS:

☒	MARKET RESEARCH
☒	COMPARISON OF PROPOSED PRICE WITH PRICES FOUND REASONABLE ON PREVIOUS PURCHASES
☒	CURRENT PRICE LIST
☒	COMPARISON WITH SIMILAR ITEMS IN A RELATED INDUSTRY
☒	COMPARISON TO IGCE
☐	CONTRACTING OFFICER'S PERSONAL KNOWLEDGE (EXPLAIN)
☐	OTHER (EXPLAIN)