

**NORTH SPRINGFIELD LAKE PAVING
U.S. ARMY CORPS OF ENGINEERS
NORTH SPRINGFIELD LAKE
SPRINGFIELD, VERMONT
STATEMENT OF WORK**

Informational Photos for Reference Only



Photo 1: Two Bay Garage Approach



Photo 2: Two Bay Garage Approach



Photo 3: Recreation Parking Entrance - Option 1



Photo 4: Recreation Parking Entrance - Option 1



Photo 5: Stoughton Pond Recreation Area - Option 2



Photo 6: Stoughton Pond Recreation Area - Options 2 & 6



Photo 7: West Access Recreation Area - Option 3




Photo 8: West Access Recreation Area - Option 3



Photo 9: West Access Recreation Area Pothole - Option 3



Photo 10: East Access Entrance Road - Option 4



Photo 11: East Access Entrance Road - Option 4



Photo 12: East Access Entrance Rd. Culvert Cut - Option 5



Photo 13: East Access Entrance Rd. Culvert Cut - Option 5
Government has cut pavement and replaced culvert




Photo 14: Stoughton Pond Recreation Area Culvert Cut - Option 6
(See Photo 6 For Existing Condition)