

JUSTIFICATION FOR SOLE SOURCE
(Simplified Procedures - MPT to ≤ SAT)

Purchase Request/Document number: [REDACTED]

The supplies or services described herein are being solicited on a sole source basis and competition is precluded in accordance with FAR 12.102(a) for reasons indicated below. There are no substitutes available for the supplies or services.

Restricted to the following source.

☒ **Service:**

Contractor:	Wood's CRW Corp.
Cage Code:	3CXG9

☐ **Supply:**

Original Manufacturer Name:	
☐ Check here if obtaining product through authorized resellers of the manufacturer.	

Description of the supplies or services required, the estimated price/cost, and required delivery date or period of performance.

Naval History and Heritage Command, Detachment Boston (NHHADB) is the maintenance and repair facility supporting the USS CONSTITUTION. As part of that function, NHHADB owns a LINKBELT Crane Model RTC80130 used to rig the ship, lift on various items in support of the ship and support the ships underway movements. NHHADB's LINKBELT Crane Model RTC80130 requires the crane to be sent to the contractor facility to rebuild the nonoperational crane hydraulic swivel.

This requirement represents the minimum requirements of the Government with a total estimated price of [REDACTED]

Describe in detail why only this source(s) can furnish the requirements to the exclusion of other sources.

NHHADB requires the LINKBELT Crane Model RTC80130 to be serviced by an original equipment manufacturer (OEM) certified contractor for LINKBELT cranes. Per Naval Facilities, NAVFAC, Navy Crane Center, Weight Handling Management Manual P-307, Chapter 10.8.3: During all phases of assembly/disassembly, all OEM requirements pertaining to assembly/disassembly and any additional AEPs shall be followed. If OEM procedures are not available, the assembly/disassembly procedures shall be reviewed by the Navy Crane Center, Code 03. The rated capacity of the crane, equipment components (including rigging), lifting lugs, and equipment accessories shall not be exceeded.


☒ The supplies or services must be compatible in all aspects (form, fit and function) with existing systems presently installed/performing. Describe the equipment/function you have now and how the new item/service must coordinate, connect, or interface with the existing system.

NHHADB's LINKBELT Crane Model RTC80130 is primarily used to rig the ship, lift on various items in support of the ship and support the ships' underway movements. Currently, the crane's hydraulic swivel does not operate, and the crane cannot operate its outriggers. Therefore, it needs to be rebuilt. Woods CRW is a specifically certified OEM that has been certified and approved by LINKBELT and meets the Navy Crane Center requirement. They have been servicing NHHADB's LINK Belt Crane since it was obtained and are the only known responsive vendor in the area to provide the unique maintenance services. To ensure that the crane maintenance is consistent with previous work done, the crane should be serviced by the vendor that has performed maintenance on it since its initial acquisition. Attempting to find

another OEM certified vendor that meets the Navy Crane Center requirements in the Northeast region would cost the Government additional unnecessary time and funding to familiarize them with NHHCDB's LINK Belt crane.

TECHNICAL/REQUIREMENTS CERTIFICATION:

I CERTIFY THAT THE INFORMATION PROVIDED ABOVE IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE. I UNDERSTAND THAT THE PROCESSING OF THIS SOLE SOURCE JUSTIFICATION PRECLUDES THE USE OF FULL AND OPEN COMPETITION.



Signature

16 APR 2026

Date

NHHC DET BOSTON

Activity

DIRECTOR

Title

I HEREBY DETERMINE THAT THE CIRCUMSTANCES OF THE CONTRACT ACTION DEEM ONLY ONE SOURCE REASONABLY AVAILABLE IN ACCORDANCE WITH FAR 13.106-1(b)(1)(i).

ELLIS.CODY.CAMERO

N.1559662182

Digitally signed by
ELLIS.CODY.CAMERON.1559662182
Date: 2026.05.05 19:34:43 -04'00'

Contracting Officer Signature

Date

NAVSUP Fleet Logistics Center, Norfolk Contracting
Department, Fleet Directorate