

Attachment A: PRE-QUALIFYING INTERIM LIFE SAFETY MEASURES ASSESSMENT (PQIA) AND INTERIM LIFE SAFETY MEASURES (ILSM) WORKSHEET

Project:

660-26-220 Replace FF&E IPU

Project Start

Project End

Date: TBD

Date: TBD

Other Identifying Information about the project:

Replacement of plumbing fixtures, doors, and ceiling systems within the IPU to address MHEOC findings.

Person Completing
Assessment:

Zane Kozarec

Step 1: Go to section 1 and perform PQIA.

Based on PQIA is an ILSM required?				
YES	X	Document ILSM Number Here:	I-2025-	
NO		Document PQIA Number Here:	P-2025-	

If answer to the above question is **YES**, an ILSM and further action is required. Complete Section 2. Enter the ILSMA number above. Additionally, document ILSM number and the required narrative in the ILSM.PQIA tracking spreadsheet.

If answer to the above question is **NO**, an ILSM and further action is not required. Enter the PQIA number above. Additionally, document PQIA number and the required narrative in the ILSM.PQIA tracking spreadsheet.

If optional ILSM implementation is elected for PQIA answered NO, complete Section 2.

Section 1: Pre-Qualifying Interim Life Safety Measures Assessment (PQIA)

Indicate selections by highlighting selected blocks in yellow. *More than one may be selected.*

A Value, Life Safety Deficiency, Service, or Impairment Risk Score			
Deficiency, Failure, Draining or Disabling of:		Other Risk Factors:	
Any one fire alarm initiating device	1	Inaccessible damper	2
Any one supervisory Sprinkler device	1	Exit light out/to be installed or repaired	2
Multiple sprinkler devices (more than 1, less than a whole zone)	2	Battery operated egress light egress light repair/replace/install	2
Multiple initiating device (more than 1, less than a whole zone)	2	Cutting metal, Welding, brazing, soldering – requires hot work permit	4
A fire sprinkler system taken out of service for more than 10 hours in occupied building	4	HVAC system does not shut down upon fire alarm condition	3
A fire alarm system taken out of service for more than 8 hours in occupied building	4	Broken rolling or sliding door	3
A fire sprinkler system taken out of service for less than 10 hours in occupied building	3	Penetration in fire wall	4
A fire alarm system taken out of service for less than 8 hours in occupied building	3	Penetration in smoke wall	3
The off-site notification feature of a fire alarm zone or system out of service for 4 or more hours	4	Corridor door latching problems	2
The off-site notification feature of a fire alarm zone or system out of service for less than 4 hours	3	Compromised smoke or fire compartment	3
Water storage tank low water or temperature alarm failure	3	Blocked exit due to repairs needed or another physical hazard	4
A main drain from the sprinkler system	3	Removal of ceiling tiles for 4 or more hours in sprinkled space	4
A standpipe or sprinkler connection	3	Smoke or fire door or chute door missing rating	1
A dry pipe extinguishing system	3	Deck missing fireproofing	2
A wet pipe extinguishing system	3	Light lens cover missing from in egress path fixture	1
All or part of an Ansul (hood fire protection) system	3	Exit/stairs blocked or deficiencies	4
Fire or smoke dampers	3	Egress path blocked/rerouted	4
Any 1 visual or audible fire alarm notification device	1	Fire door deficiency	3
More than 1 visual and/or audible fire alarm notification device	3		

B Occupancy Weight Score			
Operating Room	4	Ambulatory Patient Care Unit	2
Intensive Care Unit	4	Outpatient Surgery	2
Same Day Surgery (Recovery)	4	Sleep Lab Outpatient	2
Inpatient Care Unit	4	Behavioral Health Residential	1
Hospital Occupancy	4	Behavioral Health Outpatient	1
Community Living Center	4	Outpatient Clinic (CBOC)	1
Ambulatory Occupancy	3	Ancillary Support Business	1
Special Procedures	3	Business Occupancy	1
Emergency Room	3		
MRI	3		

Section 1: Pre-Qualifying Interim Life Safety Measures Assessment (PQIA) - Continued

Value A and Weight B Metric Scoring (Select from Charts)

11	+	1	=	12
Value A		Weight B		Risk Score

Risk score 1-7

☐ No further action required

Risk score 8 or higher

☒ ILSM assessment required

Section 2. Interim Life Safety Measure Assessment

Use the ILSM Assessment Matrix as a guideline to determine which ILSM(s) will be implemented.

1.	Ensure Emergency Egress
2.	Ensure Emergency Forces Access
3.	Notify Emergency Forces (VAFD)
4.	Notify Staff
5.	Ensure Operational Life Safety Systems
6.	Post Fire Watch *
7.	Temporary Construction Barriers
8.	Provide Additional Fire Fighting Equipment
9.	Control Combustible Loading
10.	Conduct Additional Fire Drill(s) *
11.	Increase Surveillance *
12.	Provide Temporary Fire Alarm and Detection System (Inspection and Testing Documentation) *
13.	Conduct Additional Life Safety Training *
14.	Other

*Additional Documentation Required

Description of action taken:

ILSM Started: _____ Estimated Date of Completion: _____

☐ Verification that ILSM hazard corrected/work complete. Date: _____
 Name: _____ Title: _____

Section 2. Interim Life Safety Measure Assessment (Continued)

Significant Life Safety Code Deficiencies Result from Construction or Other Events.	1) Ensure Egress	2) Ensure Emergency	3) Notify Emergency Forces (VAFD)	4) Notify Staff	5) Ensure Operational Life Safety Systems	6) Fire Watch*	7) Temporary Construction Barriers	8) Provide Additional Fire Fighting Equipment	9) Control Combustible Loading	10) Conduct Additional Fire Drill(s) *	11) Increase Surveillance *	12) Provide Temporary Fire Alarm and Detection System *	13) Conduct Additional Life Safety Training	14) Other
Construction/major renovation	X	X	X	X	X		X	X	X	X	X	X	X	
Lacking a code-complying smoke barrier			X	X	X				X					
Fire exit stairs discharge deficiency	X	X	X	X	X				X				X	
Excessive travel distance to an approved exit	X		X	X					X					
Lack of two remote exits	X	X	X	X	X				X	X			X	
Non-conforming building construction type			X		X				X					
Penetrations in fire barriers			X						X					
Hazardous areas not properly protected		X	X	X					X		X			
Fire /Smoke Door Deficiency			X						X		X			
Blocking off an approved exit/egress path	X	X	X	X	X			X	X	X	X		X	
Improperly protected vertical openings.			X		X				X					
Fire alarm/detection system (out of service)		X	X	X	X	X	X	X	X		X	X	X	
Sprinkler system (out of service)	X	X	X	X	X	X	X	X	X		X	X	X	
Panel showing common trouble			X		X				X					
Off-site notification alarm failure			X		X						X			
Smoke partition deficiency			X	X	X				X					
Hot work permit required			X		X			X	X					
Other Life Safety Deficiency not identified above														

*This form is a guide for ILSM implementation, however, based on the project scope and/or life safety code deficiency, the ILSM to be implemented may be expanded or reduced from what this table indicates.