

Semi Annual Inspection Report

Completed on: 12-22-2025

for

VA Grand Junction Building 1
2121 North Ave
Grand Junction, CO 81501-6428

Conducted By:

James Trudeau
Platinum Fire Protection
PO Box 607
Mead, CO 80542

This Joint Commission inspection was performed in accordance with the following codes and regulations:

- NFPA 25 2011 - Standard for the Inspection, Testing, and Maintenance of Water Based Fire Protection Systems

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiencies - General Questions

Deficiency #1

Are the gauges on system in good condition and showing normal water supply pressure? - 5.2.4.1: No

Notes: 55 gauges were recently replaced. Found an old one in stair 9 mechanical room 1633 on the main riser. Stair 1 basement has 1 old gauge that's due for replacement, and 2 that weren't replaced but not due until 2027

Deficiency #1 - Photo #1



Date Taken: December 15, 2025

Deficiency #2

The electrical waterflow alarm devices passed test by opening inspector's test connection/bypass connection with alarms actuating and flow observed? - 5.3.3.3: No

Notes: Stair 2 4th fl need test and drain assembly replaced. Its damaged and missing handles and leaks when used
Stair 4 2nd fl drain pipe from test and drain leaks so bad it makes a water mess on the floor at the staircase door and is dangerous to walk. Pipe is rotted and needs to be replaced with a new test and drain valve.
Stair 4 third floor needs a new test and drain valve. The drain handle is broken and missing.
Stair 1 2nd fl test and drain needs to be replaced. Handles missing and always leaks. It's overtightened so badly now we can't get it open without risking catastrophic damage.
Stair 3 first floor has damaged inspectors test valve. Recommend replacement
Stair 9 first and second floor need new inspectors test valves.

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #3

Have the mechanical waterflow alarm devices passed tests by opening inspector's test connection/bypass connection with alarms actuating and flow observed? - 5.3.3.3: No

Notes: Stair 2 4th fl need test and drain assembly replaced. Its damaged and missing handles and leaks when used
Stair 4 2nd fl drain pipe from test and drain leaks so bad it makes a water mess on the floor at the staircase door and is dangerous to walk. Pipe is rotted and needs to be replaced.
Stair 1 2nd fl test and drain needs to be replaced. Handles missing and always leaks. It's overtightened so badly now we can't get it open without risking catastrophic damage.

Deficiency #4

Are the control valves (including valves on backflow preventers) with locks or electrical supervision properly identified? - 13.3.2.2: No

Notes: All valves in the pump house missing signs
Many inspectors test locations not marked with signs

Deficiency #5

Are alarms and supervisory devices not damaged? - 5.2.5: No

Notes: Stair 2 fifth floor flow switch doesn't activate after 150 seconds of flowing water. Needs to be investigated and possibly replaced
Stair 9 third floor flow switch taking longer and longer each time it's tested. Recommend replacement.
Stair 1 basement standpipe control valve tamper switch doesn't report to FACP

Deficiency #6

Are the control valves (including valves on backflow preventers) with locks or electrical supervision accessible? - 13.3.2.2: No

Notes: Many of the older OS&Y valves in stair 3 are very difficult to operate, even with the chain system. We will lubricate again in August but doubt they will change much.
Update, still very difficult to operate

Deficiencies - General Wet System Questions

None

Deficiencies - Wet

Deficiency #7

Sprinkler Type: Wet

Did waterflow alarm operate? - 13.2.6: No

Notes: 5th fl stair 2 flow switch does not activate after 2.5 minutes of flowing.

Deficiency #8

Sprinkler Type: Wet

Is flow observed? - 13.2.5: No

Notes: Some drain valves leak or missing handles need to be replaced so they can be tested quarterly without creating damage or water problems. See individual floor reports

Deficiencies - Inspectors Test Connection

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #9

Location: Stair 1
Description: 4th fl
Signs: No

Notes:

Deficiency #10

Location: Stair 4
Description: 1st fl
Signs: No

Notes:

Deficiency #11

Location: Stair 2 ceiling above drinking fountain
Description: 2nd fl
Signs: No

Notes:

Deficiency #12

Location: Stair 1
Description: 3rd fl
Signs: No

Notes: No sign on ceiling tile

Deficiency #13

Location: Stair 8
Description: 3rd fl
Signs: No

Notes: No sign

Deficiency #14

Location: Stair 1
Description: 1st fl
Signs: No

Notes: No sign on ceiling tile
Bad inspectors test valve. Leaks badly. Recommend replacement

Deficiency #15

Location: Stair 2
Description: Crawl space
Signs: No

Notes: No sign
Main drain 107/55/107

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #16

Location: Stair 2
Description: 3rd fl
Signs: No

Notes: No sign on ceiling tile
Main drain 79/55/80

Deficiency #17

Location: Stair 2
Description: 5th fl
Pass?: No
Was alarm reported?: No
Signs: No

Notes: No sign
No alarm after 2.5 minutes of flow. Recommend replacement. Very high up.
Main drain 80/55/80

Deficiency #17 - Photo #1



Date Taken: August 18, 2025

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #18

Location: @ 5005

Description: 5th fl psych area

Terminates in Smooth Orifice?: No

Easily Accessible?: No

Signs: No

Notes: No sign on ceiling tile.

No inspectors test valve found. Manual trip onl

Deficiency #19

Location: 3rd fl ceiling @ elevator

Description: 3rd fl

Signs: No

Notes: No sign on ceiling tile

Main drain 102/57/100

Deficiency #20

Location: Stair 8

Description: 2nd fl

Signs: No

Notes: No sign

Deficiency #21

Location: Stair 4

Description: 2nd fl

Was alarm reported?: No

Signs: No

Notes: No sign.

Pipe on outlet of test valve is rotted and leaves a large puddle on hallway floor causing a potential fall hazard.

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #21 - Photo #1



Date Taken: August 18, 2025

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #21 - Photo #2



Date Taken: December 15, 2025

Deficiency #22

Location: Stair 9

Description: 1st fl

Signs: No

Notes: No sign.

Inspectors test damaged on both drain and test. Needs to be replaced. Also had internal damage and is very difficult to close

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #22 - Photo #1



Date Taken: July 09, 2025

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #22 - Photo #2



Date Taken: August 18, 2025

Deficiency #23

Location: Stair 2 ceiling

Description: 4th fl

Pass?: No

Was alarm reported?: No

Notes: Inspectors test valve broken. Can't even use channel locks because brass stem is missing. Needs new valve.

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #23 - Photo #1



Date Taken: August 18, 2025

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #23 - Photo #2



Date Taken: December 15, 2025

Deficiency #24

Location: Stair 8
Description: 1st fl
Signs: No

Notes: No sign

Deficiency #25

Location: Pump house
Description: Pump house sprinklers
Signs: No

Notes: Main drain test
198/65/209 with pump off

Deficiency #26

Location: Stair 1
Description: 2nd fl
Signs: No

Notes: No sign on ceiling tile

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #27

Location: Stair 9


Description: 2nd fl

Signs: No

Notes: No sign

Inspectors test valve in poor condition, now handle is completely broken. Using channel locks for now but will soon be untestable until replaced

Deficiency #27 - Photo #1



Date Taken: August 18, 2025

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #27 - Photo #2



Date Taken: December 15, 2025

Deficiency #28

Location: Stair 9

Description: 3rd fl

Pass?: No

Signs: No

Notes: Alarm time needs to be closer to 45 seconds. Likely needs new flow switch

No sign

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #28 - Photo #1



Date Taken: July 09, 2025

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #28 - Photo #2



Date Taken: August 18, 2025

Deficiency #29

Location: Pharmacy

Description: 1st fl

Signs: No

Notes: No sign on ceiling tile
Main drain 100/50/100

Deficiency #30

Location: Stair 1

Description: 5th fl

Signs: No

Notes: No sign on ceiling tile

Deficiency #31

Location: Stair 3 ceiling @ elevator

Description: 4th fl

Signs: No

Notes: No sign on ceiling tile
Main drain 100/48/100

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #32

Location: @ stair 3 ceiling

Description: 1st fl

Signs: No

Notes: Inspectors test valve is old and handles broken and doesn't seal well. Recommend replacement
No sign on ceiling tile
103/49/104

Deficiency #33

Location: 2nd fl @ stair 3

Description: 2nd fl

Signs: No

Notes: No sign on ceiling
100/52/99

Deficiencies - Valves

Deficiency #34

Location: Pump house

Valve Type: Butterfly

Size: 6

Description: Pump bypass #1

Signs: No

Notes: No sign

Deficiency #35

Location: Stair 9

Valve Type: Butterfly

Size: 3

Description: 3rd fl

Signs: No

Notes:

Deficiency #36

Location: Stair 9

Valve Type: Butterfly

Size: 4

Description: Mechanical room stair 8 feed

Signs: No

Notes:

Deficiency #37

Location: Stair 9 mechanical room

Valve Type: Butterfly

Size: 4

Description: Stair 9 standpipe

Signs: No

Notes:

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #38

Location: Pump house
Valve Type: Butterball
Size: 1
Description: Pump house sprinklers
Signs: No

Notes: No sign

Deficiency #39

Location: Loading dock basement
Valve Type: OS&Y
Size: 8
Description: Backflow #1
Signs: No

Notes: No sign

Deficiency #40

Location: Dock basement
Valve Type: OS&Y
Size: 8
Description: Backflow #2
Signs: No

Notes: No sign

Deficiency #41

Location: Stair 9
Valve Type: Butterfly
Size: 4
Description: 2nd fl
Signs: No

Notes: No sign

Deficiency #42

Location: Pump house
Valve Type: OS&Y
Size: 8
Description: Pump suction
Signs: No

Notes: No sign

Deficiency #43

Location: Ceiling @ 5005
Valve Type: Butterfly
Size: 2-1/2
Description: Psych ward control
Signs: No

Notes: No sign on ceiling tile

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #44

Location: Pump house
Valve Type: Butterfly
Size: 6
Description: Pump discharge
Signs: No

Notes: No sign

Deficiency #45

Location: Stair 2
Valve Type: OS&Y
Size: 3
Description: 1st fl
Easily Accessible?: No

Notes: Very difficult to operate. Should be replaced

Deficiency #46

Location: Pump house
Valve Type: Butterball
Size: 1-1/4
Description: Jockey pump discharge
Signs: No

Notes: No sign

Deficiency #47

Location: Pump house
Valve Type: Butterfly
Size: 6
Description: Bypass #2
Signs: No

Notes: No sign

Deficiency #48

Location: Pump house
Valve Type: Butterfly
Size: 6
Description: Pump meter
Signs: No

Notes: This is a normally closed valve that doesn't trigger the tamper until it's fully open.
No sign.

Deficiency #49

Location: Stair 3
Valve Type: OS&Y
Size: 3
Description: 4th fl
Exercised?: No

Notes: Very difficult to operate. Recommend replacing

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #49 - Photo #1



Date Taken: August 18, 2025

Deficiency #50

Location: Pump house

Valve Type: Butterfly

Size: 6

Description: Test header

Signs: No

Notes: Normally closed valve doesn't signal tamper until fully opened.

No sign

Deficiency #51

Location: Stair 1

Valve Type: OS&Y

Size: 3

Description: 1st fl

Exercised?: No

Notes: Valve very difficult to operate. Should be replaced

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #51 - Photo #1



Date Taken: July 09, 2025

Deficiency #52

Location: Pump house

Valve Type: Butterball

Size: 1-1/4

Description: Jockey pump suction

Signs: No

Notes: No sign

Deficiency #53

Location: Stair 3

Valve Type: OS&Y

Size: 3

Description: 1st fl

Exercised?: No

Notes: Very difficult to operate. Recommend replacement

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #53 - Photo #1



Date Taken: August 18, 2025

Deficiency #54

Location: Pump house

Valve Type: Butterfly

Size: 6

Description: Pump meter suction

Signs: No

Notes: This is a normally closed valve that doesn't trigger tamper until it's fully open.

No sign

Deficiency #55

Location: Stair 3

Valve Type: OS&Y

Size: 3

Description: 7th I

Exercised?: No

Notes: Very stiff and difficult to operate. Recommend replacing

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #55 - Photo #1



Date Taken: August 18, 2025

Deficiency #56

Location: Stair 2 crawl space
Valve Type: OS&Y
Size: 6
Description: Bldg 1 standpipe
Signs: No
Exercised?: No

Notes: No sign

Deficiency #57

Location: Pump house
Valve Type: Butterfly
Size: 6
Description: Pump bypass #1
Signs: No

Notes: No sign

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #58

Location: Stair 8
Valve Type: Butterfly
Size: 3
Description: 3rd fl
Signs: No

Notes: No sign

Deficiency #59

Location: Stair 1
Valve Type: OS&Y
Size: 6
Description: Basement standpipe
Signs: No

Notes: No sign

Deficiency #60

Location: Stair 1
Valve Type: OS&Y
Size: 3
Description: 2nd fl
Easily Accessible?: No

Notes: Very difficult to operate. Needs replacement

Deficiency #61

Location: Stair 4
Valve Type: OS&Y
Size: 6
Description: Crawl space
Signs: No

Notes: No sign

Very difficult to operate. Recommend replacing

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Deficiency #61 - Photo #1



Date Taken: August 18, 2025

Deficiency #62

Location: Stair 2 crawl space

Valve Type: Butterball

Size: 2-1/2

Description: Basement

Signs: No

Notes: No sign

Report of Inspection / Test

Semi-Annual NFPA 25

12-22-2025

Property

VA Grand Junction Building 1
2121 North Ave
Grand Junction CO 81501-6428

Print Date: 12-23-2025

Conducted by: James Trudeau

Platinum Fire Protection
PO Box 607
Mead CO 80542
3036880177
rachel@platfire.com



Inspector Signature

I state that the information on this form is correct at the time and place of my inspection, and all equipment tested at this time was left in operational condition upon completion of this inspection except as noted.

Inspector Name	Signature	Date Completed
James Trudeau		2025-12-22