

Pictures of the Rawlins Field Office Interior and Exterior



Figure 1. Rawlins Field Office



Figure 2. Rooftop HVAC Units (RTU-1 and RTU-2)



Figure 3. Boiler (B-1) in Mechanical Room



Figure 4. Split HVAC Unit in First Floor Telecom Room



Figure 5. Rooftop Split HVAC Units (Serving Telecom and Computer Rooms)



Figure 6. Air Duct and Diffuser



Figure 7. VMA (Inside VAV Box)



Figure 8. Thermostat and CO2 Sensor



Figure 9. RTUs From North Side of Building