

Sources Sought Q&A – ACU-2 Alignment and Preventative Maintenance

- Is it located at Edwards?
 - Yes – B1030
- Is there any clearance required for working on base?
 - Yes – VCC and Compound – Form Attached must be completed 4 duty days prior to visit
- Also verifying-this service is only required once per year?
 - Yes, bearing mx, component inspection, lubrication and alignment, ops check to be completed annually.
- Is there any terms for emergency failure if the motor crashes unexpectedly? Is this contract only tied to bearing faults or would the party be responsible for electrical failures as well?
 - If the motor fails, then yes. We would like to have the vendor come out to troubleshoot and possibly repair the motor. Repair bearing and/or electrical failures with the motor only, also.
- Do you have nameplate data for the motor so we can get the exact model number and HP rating?
 - See below

BALDOR • RELIANCE

SuperE Motor

CC010A

SPEC. NO.	A44-8329-2746		CAT. NO.		FRAME SIZE	449TS			
HP	500	VOLTS	460	PHASE	3	DESIGN	B	TYPE	P
RPM	3565	AMPS	544	HZ	6-60	AMB	40 °C	SF	1.00
DRIVE END BEARING	65BC03J30X			DUTY	CONT	INSUL CLASS	F		
OPP. D.E. BEARING	65BC03J30X			ENCL	DP	CODE	F		
VARIABLE TORQUE		SER. NO.	A1802022089						
VPWM INVERTER									
SUIT FOR 1.15 SF ON SINEWAVE POWER									
OVER TEMP PROT 2									
BALDOR ELECTRIC CO., FT. SMITH, AR. MFG. IN U.S.A.						MOTOR WEIGHT	2595 LBS.		
						NP2354L			

LUBRICATED
WITH

MOBIL POLYREX EM

NP2496L