

2014 Bobcat 5600 Toolcat

SN: AHG811652

1532 hours

ECU needs to be replaced (warning light is on)

Small hydraulic leak on quick-tach

2 NOX sensors were replaced recently











