TOYOTA TANZANIA LTD.

TOYOTA Customer Order

3009

WAIT	ING

⊘ PM	2000 K	⊘ GR	☐ WR	☑ Internal	✓ Appointment	✓ Walk-in		
✓ Pick-up								
Reception		Date : 07/08/2023			Time: 19:07:00			
		Changes :						
Delivery		Date: Time:						
		Changes :						

Repair Order No.:	24		Date	17/05/2023
Service Invitation	✓ Failed	Succeed	Date	17/05/2023
B/O Parts	12		Staff Name	afd
Appointment Confirmation	12		Staff Name	asd
Parts Ordered	12		Staff Name	abva
Parts Confirmed	12		Staff Name	cv

Customer Information			Vehicle Information				Previous Service Information				
Name	Neosao			Vehicle Reg. No.				Job Type	repair1	R/O No.	123
Address	Kolhapur			Model (Year)	2015			Odo. Read.	123	Payment	3999
Mobile TEL No. ✓	9898989898	Available Time	Date: Time: 10:20AM	Model Code				Rec. (Data & Time)	22/05/2023		
Home TEL No. ✓	12345678	Driven	✓ Owner ☐ Family	VIN No.				Del. (Data & Time)	22/05/2023 10:00		
Office TEL No. 🗸	1234567890	Ву	Others	Color Code		E/G No.	EG-123	Car Wash		Replaced Parts	part A
Email 🗸	customer@gmail.com		Sale Date	13/05/2023	DLR Code	DLR-123	SA	123	TECH		
Others 🗸	Total		SSC / SC Info.	☑ NA	Op. No.	OP-123	Tech				
J	Text text			Completed Op. No.	COP-123			Advise			

Customer's Request / Concerns (in customer words)	✓ Requ	est For TA	✓ Appointment		
	Date 22/0!	5/2023	Date		
	Time		Time		
	Staff	Name			
Job Details / Parts Replacements	Quantity	Labor Hours	Estimation		
Part A	234	2	4	100	
Part A	2	4	10		
	Labor Total 200	Parts Total 800		Grand Total	1000

Walk-around Check			Floor Mat Condition			Confirmation	Reception			
		Tools	$oldsymbol{oldsymbol{arphi}}$	Good	No Good	Replaced Parts	Yes	✓ No	Date 07/08/2023	
(100,000		Cig. lighter		☐ Non-Genuine	☐ Not Fixed	Car Wash	Yes	⊘ No	Time 19:07:00	
		Spare Wheel	0	☐ Double Mat	Others	Valuable	Yes	⊘ No		
		Radio/Cassete	0			Protective Covers	☐ Seat	Floor		
	8	Lights Condition		[]		Memo Accessories Installation			Staff	6
		Fire Extingusher		Payment Method					Name	Service Advisor
		Damages / Dent	0	Cash	Credit Card					
		No of Keys		Cheque	Others					
		Inspected By :- Service Advisor		[]					
Odometer Reading-in			0.0 Km	Fuel	EF	I have received explaination of and agree				

 ${\sf TERMS\ \&\ CONDITIONS:\ Vehicles\ and\ contents\ are\ stored\ and\ driven\ by\ our\ staff\ at\ owner's\ risk.}$

No responsibility attaches to us for loss by frost, fire, burglary, theft, accident, delay due to non-availability of material or other causes whatsoever.

If further essential work is required we will proceed at our discretion. New parts will be supplied and fitted as required. Estimates are provisional and not binding.

All manufactured goods supplied subject to the terms & condition laid down by the manufacturer.

CASH ON DELIVERY: Unless credit arrangement satisfactory to ourselves have made in advanced. An express mechanics lien is hereby acknowledge to secure the amount of repairs thereto.

"I/We authorise the itemised work to be carried out on the above vehicle and agree to the terms & condition printed herein. I/We will be responsible for payment of this account at your customary rates and charges."

Tel: +255 27 2544092 Owner Authorisation: LP.O No. Vehicle Registration No. : **Customer Care: TOYOTA** TOYOTA TANZANIA LTD 0786 869 682 **Service Advisor Phone:** Tel: 0786 TOYOTA N.B. PLEASE KEEP THIS CARD IN A SAFE PLACE IN YOUR INTEREST YOUR VEHICLES KEYS WILL NOT BE RELEASED UNLESS THIS CARD IS PRESENTED. Please remove all valuables from your vehicle.

For information on progress of your Job or Vehicle, please call Service Advisor above.