




<- this must measure exactly 100 mm. If it does not, reprint at 100% / Actual Size / Fit to printable area.

10 x 7 squares = 9 x 6 INNER CORNERS | 20 mm squares

Stereo Calibration: set Board Corner Columns=9, Rows=6, Square Size=20 mm.

Mount FLAT and RIGID. Do not trim the white border -- the corner detector needs it.