Vertical Bandsaw Blade Mending


By Chanoon Likitsuwanmon 4/15/2024

Purpose

So that members of our team know how to mend a broken vertical bandsaw blade in the case that it happens to break

Procedure


1. Remove the bandsaw from the machine
    a. Open the
2. Cut the broken ends of the blade. Ensure that the gullet are similar as the others. This is two ensure that two teether aren't aligned right next to each other.



3. Welding the Blade
    a. Turn the pressure knob so that there is no pressure on the blade. The arrow



b. Place the blade inside the vice then clamp the blades. Make sure that the blades are as close to touching each other as possible. The blades being flush would be ideal




c. With the blades together, turn the pressure dial. The amount of pressure depends on the size of the blade. The knob should be turned around 1/3 of the way.



d. Hit the weld button so that the two blades are welded together. The weld should've created a ridge which will need to be grinded out.

4. Turn on the switch for the grinder. It should be located near the grinder itself, under the welder.
5. As you grind make sure to be gentle and DON'T bend the blade as the point at which the blade was welded would be very brittle.
    a. Make sure to grind every side including the spine so that the blade is square.

6. Anneal the Bandsaw blade
    a. Re-clamp the blade where previously you welded it.
    b. On the Pressure Knob set it to even less pressure than
    c. When pressing the anneal button make sure that the blade turns red and not bright orange. This process needs to be done 3 times. You might need to anneal the blade more than 3 times if it is larger.



Remember that this process should be done under the supervision of an adult.