Correspondence Thread: Kasargod Depot - Tank Calibration Discrepancy

Thread ID: CORR-KGD-2026-0091 | Depot: Kasargod (Kerala) | Status: Pending HQ Approval

From: S. Nair (Depot Manager, Kasargod) To: Marketing Ops, HQ Mangalore Date: 2026-04-11 09:14

During the scheduled quarterly tank calibration for Tank TK-K-03 (MS storage, 500 KL nominal), the third-party calibration agency's dip-chart figures show a variance of 0.6% against the previous calibration certificate. Requesting guidance on whether this falls within acceptable tolerance or requires re-calibration before the tank is returned to receipt service.

From: R. Kamath (Marketing Ops Manager, HQ) To: S. Nair, Kasargod Date: 2026-04-12 11:02

0.6% variance is above our internal tolerance of 0.3% for MS tanks per the Depot Operations Manual Section 5.2. Please hold TK-K-03 out of receipt service and arrange re-calibration. Confirm the calibration agency's accreditation certificate is current before proceeding.

From: S. Nair (Depot Manager, Kasargod) To: R. Kamath, HQ Date: 2026-04-14 15:47

Noted, TK-K-03 held out of service effective today. Calibration agency accreditation confirmed valid until Dec 2027. Re-calibration scheduled for 2026-04-20. Requesting temporary receipt allocation to TK-K-01 and TK-K-02 in the interim to avoid disrupting the coastal tanker schedule.

From: R. Kamath (Marketing Ops Manager, HQ) To: S. Nair, Kasargod Date: 2026-04-14 16:30

Approved - temporary reallocation to TK-K-01/02 for the interim period. Please submit the updated re-calibration certificate to HQ Marketing Ops within 48 hours of completion for the tank to be cleared back into service.

This is a synthetic, illustrative document generated for RAG/retrieval testing purposes. It does not represent an actual MRPL internal document.