Page one: hydrocracker catalyst deactivation trend summary.

WABT creep observed over the last quarter is within normal bounds.

Page two: pipeline segment Mangalore-Hassan maintenance log.

Valve V-204 was inspected on schedule, no anomalies found.