Pipeline Incident Report - Hassan Pumping Station Segment

Report No: PIR-2026-007 | Segment: Mangalore-Hassan (Petronet MHB, 363 km corridor) | Date: 2026-07-22

1. Incident Summary

A pressure drop of 4.2 kg/cm2 was recorded at the Hassan pumping station (intermediate station on the Mangalore-Hassan-Neriya-Devangonthi corridor) at 03:14 hrs on 2026-07-22. Automatic line shutdown triggered per the pipeline SCADA logic. Field inspection identified a minor seal leak at pump P-HS-02 discharge flange. No product loss to the environment was recorded; the leak was contained within the bunded pump pad area.

2. Incident History by Segment



3. Corrective Actions

Action	Owner	Target Date	Status
Replace P-HS-02 discharge flange gasket	Pipeline Maintenance	2026-07-24	Closed
Inspect all pump seals at Hassan station	Pipeline Maintenance	2026-08-05	Closed
Review seal replacement interval SOP for Hassan/Neriya stations	Process Engineering	2026-09-01	In Progress

4. Reference

Applicable SOP: Pipeline Emergency Shutdown and Restart Procedure (Mangalore-Hassan-Neriya-Devangonthi corridor). This report links to Equipment ID P-HS-02 and PipelineSegment 'Mangalore-Hassan' in the knowledge graph.

This is a synthetic, illustrative document generated for RAG/retrieval testing purposes. It does not represent an actual MRPL internal document.