

QR Code API

Development Documentation

V1.1.0

Update Records

Date	Description
2022-10-31	First Edition Release
2023-02-22	Update API
2023-04-23	Update API and demo
2024-06-20	Update API and documentation

Contents

- 1 Introduction
 - 1.1 Get the dock sweep control object
 - 1.2 Open
 - 1.3 Close
 - 1.4 Set up receiving listening
 - 1.5 Scan dock to receive monitoring class
 - 1.6 Send Command

1 Introduction

(com.common.apiutil.decode)

It includes an interface for opening and closing hard read heads and obtaining scan information.

1.1 Get the dock sweep control object

```
/**
 * @Function Get the dock sweep control object
 *
 * @Parameter context
 *
 * */
public DecodeReader(Context context)
```

1.2 Open

```
/**
 * @Function Turn on and power on the scan code read head
 *
 *
 * @Parameter
 * 1.baud: Baudrate
 *
 * @Return ResultCode: please refer the quick guidance document.
 *
 * */
public int open(int baud)
```

1.3 Close

```
/**
 * @Function Turn off and power down the scan code read head
 *
 * @Return ResultCode: please refer the quick guidance document.
 *
 * */
public int close()
```

1.4 Set up receiving listening

```

/**
 * @Function Set up data monitoring for terminal sweeping
 *
 * @Parameter listener: IDecodeReaderListener
 *
 * @Return void
 *
 * */

public void setDecodeReaderListener(IDecodeReaderListener listener)

```

1.5 Scan dock to receive monitoring class

```

/**
 * @Function Scan dock to receive monitoring class
 *
 * */

public interface IDecodeReaderListener{
    /**
     * @Parameter data
     *
     * */
    void onRecvData(byte[] data);
}

```

1.6 Send Command

```

/**
 * @Function Send command
 *
 * @Parameter data
 *
 * @Return ResultCode: please refer the quick guidance document.
 *
 * */

public synchronized int cmdSend(byte[] data)

```