Proprietary to General Electric Company
Direction 5438996-8EN, **Rev#** 9
Brivo CT385 Series Service Methods (Adv)
Module Version 3.0, **Version Date** 1/9/14

System Scanning Test

(Click Here for Summary Version)

1 Personnel Requirements

Required Persons	Preliminary Reqs	Procedure	Finalization
1	Not Applicable	30 mins	Not Applicable

2 Overview

The System Scanning Test provides the necessary steps to exercise the system and to ensure system integrity before releasing.

Last Revised:	09 January 2014

3 Preliminary Requirements

3.1 Tools and Test Equipment

Item	Qty	Effectivity	Part#	Manufacturer
Phantom holder	1	-	2331933-2	-
Quality Assurance Phantom	1	-	5498268	-
Quality Assurance Phantom	1	-	2144715	-
Bubble Level	1	-	-	-

3.2 Required Conditions

Condition	Reference	Effectivity
Recommend procedure completion by trained personnel.	-	-

4 Procedure

4.1 Phantom Setup

1. Record phantom serial number on *System Scanning Test Report*.
2. Perform *Center Phantom*.

4.2 Acquire Scans

1. Select [NEW PATIENT] from bottom of Scan Monitor.
2. Type following entries in listed *Patient Information* fields:
    a. Patient ID: **Service**
    b. Patient Name: **System Scanning Test**
3. Select *Service* tab from *Protocol Selection, Anatomical Selector*.
4. Select [MANUFACTURING] from Service tab.
    a. If [SERVICE SYSTEM SCANNING TEST] exists, perform Using Service System Scanning Test Protocol.

b. If [SERVICE SYSTEM SCANNING TEST] does not exist, perform Using System Scan/Cust Qual Reli Protocol.

NOTE: Not all software releases have the protocol as of the release of this procedure.

4.2.1 Using Service System Scanning Test Protocol

1. Select [SERVICE SYSTEM SCANNING TEST] from [MANUFACTURING].
2. Press [CONFIRM].
3. Press [MOVE TO SCAN] on GSCB when it flashes.
4. Press [START] on GSCB when it flashes. First Scout scans are performed.
5. Press [MOVE TO SCAN] on GSCB when it flashes.
6. Press [START] on GSCB when it flashes. Second Scout scans are performed.
7. Press [NEXT SERIES]
8. Press [CONFIRM].
9. Press [MOVE TO SCAN] on GSCB when they flash.
10. Press [START] on GSCB when it flashes. Axial scans are performed.
11. Press [NEXT SERIES]
12. Press [CONFIRM].
13. Press [MOVE TO SCAN] on GSCB when they flash.
14. Press [START] on GSCB when it flashes. Helical scans are performed.
15. Select [END EXAM].
16. If a *PPS Response* window is displayed, select [COMPLETE].

4.2.2 Using System Scan/Cust Qual Reli Protocol

1. Select [SYSTEM SCAN/CUST QUAL RELI] from [MANUFACTURING].
2. Modify Series 1 - Scout as follows:

   NOTE: All Scout protocols are modified.

   a. Click [START LOC].

   b. Enter S80 and press [ENTER].

   c. Click [END LOC].

   d. Enter I80 and press [ENTER].
3. Press [CONFIRM].
4. Press [MOVE TO SCAN] on GSCB when it flashes.
5. Press [START] on GSCB when it flashes. First Scout scans are performed.
6. Press [MOVE TO SCAN] on GSCB when it flashes.
7. Press [START] on GSCB when it flashes. Second Scout scans are performed.
8. Press [NEXT SERIES]
9. Delete Groups 3 and 4 of Series 2.

   a. Select Groups 4 and click [DELETE SELECTED GROUP].

b. Select Groups 3, if not already selected, and click [DELETE SELECTED GROUP].

10. Modify Series 2 - Axial as follows:

    NOTE: All Axial protocols are modified.

    a. Click [START LOC].

    b. Enter I12.130 in Group 1.

    c. Enter I17.308 in Group 2.

11. Press [CONFIRM].
12. Press [MOVE TO SCAN] on GSCB when they flash.
13. Press [START] on GSCB when it flashes. Axial scans are performed.
14. Press [NEXT SERIES]
15. Modify Series 3 - Helical as follows:

    NOTE: All Helical protocols are modified.

    a. Click [START LOC].

    b. Enter S70 and press [ENTER].

16. Press [CONFIRM].
17. Press [MOVE TO SCAN] on GSCB when they flash.
18. Press [START] on GSCB when it flashes. Helical scans are performed.
19. Select [END EXAM].
20. If a *PPS Response* window is displayed, select [COMPLETE].

4.3 Image Review

1. From *ImageWorks* desktop, review all images from exam for unusual artifacts (rings, streaks, shading, cupping, noise, or center artifacts).

   NOTE: If any artifacts are identified, perform appropriate corrective action to resolve problem and retest.

2. Record results on *System Scanning Test Report* and store with system history records.

5 Finalization

No finalization steps.

Back to top