


# Phase method ladder: detectors -> accepted fusion -> EI

Branch rows use holdout AP when fixed-FPR recall is unavailable; fusion and EI use the low-FPR operating metric.

X/Ku GBAD Tabular ML Accepted fusion  
S-band Acoustic Seq. ML EI

LCB-aware low-FPR recall or AP diagnostic



Same three scenario panels make the progression readable: human detectors, accepted fusion, then EI.