	SOP Te	emplate								
Company Name	Process Name	Date Created	Revision Number							
One Touch Automation	Site Audit - Post Drywall	5/17/24	V1							
	Process Frequency (Daily/W									
		: Based	300)							
		Description								
To outling the the	audit process after the inst	<u> </u>	a the rough in phase							
	Involved		re the inputs?							
Name	Department or Function		oproval, Labor, Software, Etc.							
Project Manager	Project Manager		e, ToDoist, D-Tools, QB Time							
1 Toject Manager	1 Toject Manager	·	design package							
	1	T Cough in	acoign package							
	†									
	†									
	What are the se	quential steps?								
	Step Description		Who is Responsible?							
	PRIOR TO AUDIT									
	er, copy all Rough-In documentation	to the "2_Post-Drywall Audit"								
folder.			Project Manager							
Schedule site audit from project I			Project Manager							
On your iPad, in PDF Expert, sav	e that folder for offline use.		Project Manager							

0 " "D DDF F 1	***ON-SITE AUDIT***		D : 4M							
	nd select the Post-Drywall audit folde	er in the site audits folder.	Project Manager							
Perform Post-drywall site audit (u	Project Manager									
While auditing, mark up the docu	Project Manager									
- Marked with RED = Miss	Project Manager									
- Marked with ORANGE =	Project Manager									
- Marked with GREEN = A	Project Manager									
	POST AUDIT									
Update task list (if needed)	Project Manager									
Update RFI list (if needed)	Project Manager									
Update Monday.com status	Project Manager									
Opuate Monday.com status	Froject Manager									
			+							
			+							
			<u> </u>							
What ar	e the outputs [Defined Stand	dards of Completion or D	eliverables]							
Site audit has been completed	,	1 7000000	•							
Punchlist has been updated (if a	pplicable)									
Monday.com project status has b										
, special states in the second										
	Who does the process transfer to next?									
	Will does the block									
Name			Milestone							
Name Project Manage	Department	or Function Manager	Milestone Project Status Update							

_							
L							