


## Calibrating the projector




Open the starboard software from the start menu.



Choose "Calibrate" from the list of options.



Press "OK" when asked if you want to calibrate.



Press the targets using the starboard pen. Press okay when done.