







Queue composition
















Count of results by results









Kilimani

Sokoto


Gender disperaties related to water collectors




Total province per crime




gender desparities of crime



Count of time_of_crime by hour of the day



by day_of_the_week



Maji ndogo National water Survey results

Sum of Budgeted_improvement_cost

147M


province_name


High impact summaries:


What will it cost?

What will we get that money?











improvement	Sum of Budgeted_improvement_cost
Diagnose local infrastructure	2554475
Drill well	38862000
Install 1 taps nearby	2862000
Install 2 taps nearby	1654000
Install 3 taps nearby	2502000
Install 4 taps nearby	3760000
Install 5 taps nearby	4220000
Install 6 taps nearby	4626000
Install 7 taps nearby	6895000
Install 8 taps nearby	16504000
Install RO filter	39965100
Install UV and RO filter	22332800
Total	146737375


Total	146737375
Amanzi	13428275
Hawassa	22553325
Akatsi	31355075
Kilimani	39249225
Sokoto	40151475
province_name	Sum of Budgeted_improvement_cost


Sum of Budgeted_improvement_cost by province_name



SOKOTO REPORT








town	Count of Aggregated_Improvements	Sum of Budgeted_improvement_cost
Bahari	254	1204700
Cheche	207	969000
llanga	415	1768950
Kofi	278	1394350
Majengo	332	1555550
Marang	265	1183900
Rural	3852	32075025
Total	5603	40151475


Aggregated_Improvements	Sum of Budgeted_improvement_cost
Drill well	19796500
Install public tap(s)*	8214000
Install RO filter	7066500
Install UV and RO filter	4692800
Repair infrastucture	381675
Total	40151475


Sum of Budgeted_improvement_cost

40M

AMANZI REPORT








town	Count of Aggregated_Improvements	Sum of Budgeted_improvement_cost
Abidjan	212	691300
Amina	589	1286100
Asmara	503	1722900
Bello	246	960300
Dahabu	200	1251750
Pwani	296	905500
Rural	1702	6610425
Total	3748	13428275


Install public tap(s)*5900000Install RO filter2946300Drill well2592500Install UV and RO filter1102400Repair infrastucture887075
Drill well 2592500 Install UV and RO filter 1102400
Install UV and RO filter 1102400
Repair infrastucture 887075
Total 13428275


Sum of Budgeted_improvement_cost

13M

KILIMANI REPORT








town	Count of Aggregated_Improvements	Sum of Budgeted_improvement_cost
Amara	440	1607850
Harare	533	1834050
Isiqalo	499	1786250
Mrembo	655	2332650
Rural	4033	28331025
Zuri	540	3357400
Total	6700	39249225


Aggregated_Improvements Sum of Budgeted_improvement_cost Install public tap(s)* 11775000 Install RO filter 10380300 Drill well 8908000 Install UV and RO filter 7680000 Repair infrastucture 505925 Total 39249225
Install RO filter10380300Drill well8908000Install UV and RO filter7680000Repair infrastucture505925
Install UV and RO filter 7680000 Repair infrastucture 505925
Repair infrastucture 505925
·
Total 39249225


Sum of Budgeted_improvement_cost

39M

Akatsi REPORT








town	Count of Aggregated_Improvements	Sum of Budgeted_improvement_cost
Harare	422	1121200
Kintampo	421	1188800
Lusaka	575	1540250
Rural	3545	27504825
Total	4963	31355075


Aggregated Improvements	Sum of Budgeted_improvement_cost
	▼ Dadgeted_improvement_cost
Install RO filter	12173700
Install public tap(s)*	10916000
Drill well	5070250
Install UV and RO filter	2820800
Repair infrastucture	374325
Total	31355075


Sum of Budgeted_improvement_cost

31M

Hawassa REPORT







town	Count of Aggregated_Improvements	Sum of Budgeted_improvement_cost
Amina	342	1100050
Deka	277	827350
Djenne	256	863200
Rural	2928	17909325
Serowe	129	329350
Yaounde	217	750350
Zanzibar	235	773700
Total	4384	22553325

Install public tap(s)* 6218 Install UV and RO filter 6038	8300 8000
Install UV and RO filter 603	
	-000
Drill well 249	აგეე
	4750
Repair infrastucture 40	5475
Total 22553	325

Sum of Budgeted_improvement_cost

23M