








Very Important!
The original SilentStepStick has a 3-terminal solder tab. The center tab is UART (C pin 14), the other two are GND. This way the UART pin is at pin 12 on the PCB. On Alex chip, this is pin 13. However, because a pin is soldered the other way! If the PD on the chip is soldered to the other side of the 3-tab terminal on the Alex chip the UART goes on pin 12, same as the original PCB. All OK!



Motor PSU 12V 2A should be sufficient.
If not connected to PC, use a mobile phone charger.
The device always have to be powered by USB.

DM Devices
Sheet: /
File: microsteage-xy-jobkicked.sch
Title: 3-axis stepper motor controller
Size: A3
Kicad E.D.A. Kicad 7.0.11
Date:
Rev: v1.0
Gd: 1.1/

