			0	1	2	3
		0	T0 V0	T8 V0	T16 V0	T24 V0
	0	·				
0	T0 V0		T0 V0	T8 V0	T16 V0	T24 V0
1	T1 V0		T1 V0	T9 V0	T17 V0	T25 V0
2	T2 V0		T2 V0	T10 V0	T18 V0	T26 V0
3	T3 V0		T3 V0	T11 V0	T19 V0	T27 V0
4	T4 V0		T4 V0	T12 V0	T20 V0	T28 V0
5	T5 V0		T5 V0	T13 V0	T21 V0	T29 V0
6	T6 V0		T6 V0	T14 V0	T22 V0	T30 V0
7	T7 V0		T7 V0	T15 V0	T23 V0	T31 V0